

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA	DATE	: 28-Oct-21
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SDU338T		
MODEL	: TOYOTA PRIUS CVT		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 27-Oct-21
		TIME	: 08:40HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehnd</i>	1	\$ 890.20	\$ 890.20
2	REAR BUMPER SIDE RETAINER <i>2H cranked</i>	2	\$ 60.30	\$ 120.60
3	REAR BUMPER REINFORCEMENT <i>Sealed</i>	1	\$ 320.80	\$ 320.80
4	REAR BUMPER REINFORCEMENT BRACKET <i>2H</i>	2	\$ 166.30	\$ 332.60
5	TAILLAMP RH <i>Repaired cranked</i>	1	\$ 530.20	\$ 530.20

1400.30 TOTAL PRICE \$ 2,194.40

1050.22 LESS 25% \$ 548.60

SUB TOTAL PRICE \$ 1,645.80

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS(SET) <i>2H</i>	1	\$ 20.00	\$ 20.00
2	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 240.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT & REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	200	
---	--	-------------	-----	--

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	200	
3	TUFF COAT	\$ 350.00	30	
4	WIRING CHECK	\$ 150.00	30	
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	

510

ESTIMATE REPORT
TOTAL PARTS COST : \$ 1,885.80
TOTAL LABOUR COST : \$ 2,720.00
TOTAL REPAIR COST : \$ 4,605.80

APPROVED DETAILS

SURVEYOR :
CONTACT NO :
PART BY PART / LUMP SUM :
NO OF DAYS :

TOTAL

\$2,720.00

FAX :

Adrian Lij
L/S 29/10/21
03 days

total: 1780.22

L/S: 1.4K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: