



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Reg Date: 23/11/18

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY #07-16
SINGAPORE 079120

Contact :-

Fax No. : 6880 4838

Estimate : QUOT202111-000029(00)

Date : 01/11/2021

Vehicle No. : SMF7730U

Make/Model : TOYOTA PRIUS HYBRID 1.8S CVT

Mileage (km) : 0

Chassis No. : ZVW506137957

Accident Date : 29/10/2021 00:00:00

Claim No. : SMZ5983P

Reference : JO202111-0026

Policy No. : 21-MM000792-R00

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Tailgate garnish	1.0	925.60	925.60 ✓
2	Rear bumper (upper)	1.0	1,213.70	1,213.70 ✓
3	Rear bumper (lower)	1.0	576.30	576.30 ✓
4	Rear Bumper clips	12.0	4.50	54.00 ✓
5	Rear bumper side cover RH	1.0	155.30	155.30 ✓
6	Rear bumper reinforcement	1.0	332.70	332.70 ?
7	Rear bumper tow cover	1.0	15.40	15.40 ?
8	RH taillamp	1.0	481.80	481.80 ✓
9	RH tail lower lamp	1.0	478.30	478.30 ✓
10	Reverse light LED	1.0	90.50	90.50 ?
11	Rear bumper retainer	2.0	117.70	235.40 ✓
12	Rear bumper side guard RH	1.0	175.10	175.10 ?
13	Rear bumper lower guard center	1.0	229.00	229.00 ?
14	Rear bumper side seal - RH	1.0	88.50	88.50 ?
List Total :				5,051.60
25% Discount S\$				1,262.86
				3,788.74

SPECIAL NET :

1 Reverse sensor

1.0 350.00 350.00 X

SPECIAL NET Total S\$:

350.00

LABOUR :

- To check wiring and lighting
- To install reverse sensor
- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts
- Spray painting on affected & replace parts

1.0 40.00 40.00 20%
1.0 40.00 40.00 ✓
1.0 700.00 700.00 50%
1.0 900.00 900.00 80%
1,680.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CONTINUE NEXT PAGE

Page 1 of 2
Acknowledged by Repairer
Signature:
Date: