



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC21009565/Vf3e2-1 Date: 11/11/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 329S	Veh. Inspected	FBN 5073J
Policy No.		Coverage (\$)	0.00
Claim No.	21/21/21/VC00/024921	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	03/11/2021
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA SNIPER T150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MH3UG0740J0126193	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90-17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/09/2021	Inspection Date	13/09/2021
Survey held at	BEAR'S GARAGE LLP 25 KAKI BUKIT ROAD 4 #03-62 SYNERGY@KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	