

(SAS-KIV)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

LKK -

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

CP(P)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/11/2021
Vehicle Reg. No.:	SHA6004A	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	26/06/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU295392	Chassis No:	KMHC851CVKU164364
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	4,479.28
Miscellaneous Items	11.00
Labour	1,760.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,250.28
+ GST 7.00% (\$\$)	437.52
Nett Amount (\$\$)	6,687.80

This claim is handled by: LIM TIEN SIONG

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Nov 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA6004A/03/11/2021 14:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID ASSY	20.00	0.00	*2,480.40 FL <i>Ly</i>
2	1		*BOOTLID EMBLEM-HYBRID	20.00	0.00	*24.30 FL <i>de</i>
3	1		*BOOTLID EMBLEM-IONIQ	20.00	0.00	*31.30 FL <i>de</i>
4	1		*REAR BUMPER	20.00	0.00	*459.40 FL <i>de</i>
5	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*394.80 FL <i>qua</i>
6	2		*REAR BUMPER REINFORCEMENT BRKT RH/LH	20.00	0.00	*276.20 FL <i>?</i>
7	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL <i>de</i>
8	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	*155.00 FL <i>?</i>
9	2		*REAR BUMPER REFLECTOR RH/LH	20.00	0.00	*82.90 FL <i>X</i>
10	1		*REAR BUMPER TOW COVER	20.00	0.00	*98.80 FL <i>de</i>
11	1		*REAR BUMPER FOGLAMP	20.00	0.00	*201.50 FL <i>?</i>
12	1		*BOOTLID COMFORTDELGRO	0.00	0.00	*35.00 F <i>de</i>
13	1		*BOOTLID 65521111	0.00	0.00	*35.00 F <i>de</i>
14	1		*BOOTLID APPS STICKER	0.00	0.00	*40.00 F <i>de</i>
15	1		*REVERSE SENSORS	0.00	0.00	*180.00 F <i>de</i>
16	1		*REAR NO.PLATE WITH TRIM COVER	0.00	0.00	*55.00 F <i>de</i>
17	2		*REAR WINDSCREEN SEALANTS	0.00	0.00	*92.00 F <i>X</i>
18	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>de</i>
19	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	0.00	0.00	*200.00 F <i>de</i>
20	1		*BOOTLID ADVERTISEMENT STICKER	0.00	0.00	*100.00 F <i>de</i>

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 5,414.85
 - List Item Discount on L Items (\$\$) 935.57

Total Parts (\$\$) 4,479.28

ComfortDelGro Engineering Pte Ltd/SHA6004A/03/11/2021 14:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			✓ 11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 800.00
2	SPRAY PAINTING	New	500 600.00
3	R/I REAR WINDSCREEN GLASSES	New	X 240.00
4	R/I REVERSE SENSORS	New	30 120.00
Gross Labour Cost (S\$)			1,760.00

ComfortDelGro Engineering Pte Ltd/SHA6004A/03/11/2021 14:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfikh 97495749
- w/ 3/11/21 @ 4:15pm
p/p resurvey before paint
Tanfikh@lhandb.com
2 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subje. to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date/Time: 03.11.2021 13:39 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4137292

JC NO 305493175

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

IESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

DUNT CARD NO.

REGN NO.:

SHA6004A

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN

03.11.2021 10:00

YR OF MANU.

26.06.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164364

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 02.11.2021

ATURE: 3P 02.11.2021

NO


LABOR CODE

00010

PB

DESCRIPTION

PANEL BEATING-SH 8056U



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHA6004A

LIMITS

Vehicle No.:

SHA6004A

Service Advisor

Signature/Date

Name of Service Advisor

ed to Service Reception upon collection