

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	TOPLIS AND HARI	DING (S) PTE LTD		Ref:	CS/TPS21011232/y3
	133 CECIL STREE #17-01A	Т		Date:	03/11/2021
	KECK SENG TOW	ER SINGAPORE 069535			
	,			Code:	TPS
1.					
	Insured Veh.	LIFT	Veh. Inspected	k	SLV 78T
	Policy No.		Coverage (\$)		0.00
	Claim No.	SNE21D200033	Excess (\$)		0.00
	Assign From	VICTOR FONG	Assign Date		03/11/2021
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5. General Information					
	Accident Date	09/10/2021	Inspection Dat	e	05/11/2021
	Survey held at	10 AMK AVE 5#03-10 AMK AUTO POINT IND PARK 2A			
	Repairer	ACCIDENT ASSIST SG			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				