

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

*Not withair
 1/Ry @ 2200h
 Penny After Rain
 -3 days*

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP21/050

Date : 15/11/2021
 Vehicle Num. : SKV 4183H
 Make/Model : MAZDA 6-2000
 Chassis/Eng# : JM6GJ1072G0213506/PE20672451
 Accident Date : 01/11/2021
 Claim No. :
 Reference : LYB/SKV4183H/AIG/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	REAR BUMPER
2.	1	REAR BUMPER BEAM
3.	2	REAR BUMPER RETAINER
4.	1	REAR BUMPER TOWING COVER
5.	5	REAR BUMPER FASTENER
6.	5	REAR BUMPER EXTENSION FASTENER
7.	5	REAR BUMPER EXTENSION GROMMET SCREW
8.	1	REAR BOOT LID
9.	1	REAR LID RUBBER
10.	1	REAR LID LOCK (UPPER)
11.	1	REAR TAILEND PANEL

41.00	1,231.50	
	538.30	X
	82.00	X
	120.00	X
8.00	40.00	X
8.00	40.00	X
8.00	40.00	X
	1,115.00	X
	135.60	X
	186.20	X
	700.10	X
	4,228.70	
	845.74	
	3,382.96	

List Total S\$:

20.00% Discount S\$:

NETT ITEMS :

1.	1	REAR EMBLEM LOGO
2.	1	REAR EMBLEM 'MAZDA 6'
3.	1	REAR EMBLEM 'SKY ACTIVE'

55.50	
74.60	
66.80	
196.90	
19.69	
177.21	

Nett Total S\$:

10.00% Discount S\$:

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LIM YEW BOO SPRAY PAINT CO.**

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP21/050

Date : 15/11/2021
 Vehicle Num. : SKV 4183H
 Make/Model : MAZDA 6-2000
 Chassis/Eng# : JM6GJ1072G0213506/PE20672451
 Accident Date : 01/11/2021
 Claim No. :
 Reference : LYB/SKV4183H/AIG/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1	REAR LID CHROME (CENTRE)		302.00 X
2.	2	REAR LID CHROME (SIDE)	150.50	301.00 X
3.	1	REAR TAILEND PANEL TEROSTAT SEALANT		54.20 X
4.	1 SET	REAR REVERSE SENSOR		250.00 X
5.	1	REAR NO PLATE (EMBOSS) + HOLDER		55.00 X
Special Nett Total S\$:				962.20
LABOUR :				
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS				120.00 X
TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS				60.00 15/
TO CHECK WATER SEEPAGE				60.00 X
TO REMOVE, CHECK & REPAIR/REPLACE EXHAUST SILENCER				120.00 X
TO REPAIR, PANEL BEAT, CUT & WELD ON REPLACED PANEL, REALIGN/ STRAIGHTEN ON AFFECTED AREA & LABOUR TO RE- PLACE ABOVE PARTS				1,000.00 300
TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR END PANEL, REAR BEAM, REAR BUMPER, REAR REVERSE SENSOR USING 2K PAINT				1,200.00 400
Labour Total S\$:				2,560.00

E. & O.E.

Total S\$: 7,082.37

=====



for LIM YEW BOO SPRAY PAINT CO.