

Hui Zhen (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Tuesday, 30 November 2021 2:31 PM
To: Hui Zhen (LKK Auto)
Subject: RE: XE 3791U Surveyed by Steve (CS/CTI21011248/Euy3)

Dear Hui Zhen,

Audit check done for XE3791U without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Hui Zhen (LKK Auto)
Sent: Tuesday, 30 November, 2021 10:46 AM
To: Simon Ho (LKKAuto)
Subject: RE: XE 3791U Surveyed by Steve (CS/CTI21011248/Euy3)

Dear Simon,

For your reaudit.

Repairer able to undertake repair cost not more than \$63,000 on Lump sum basis.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto)
Sent: Monday, 8 November 2021 2:08 PM
To: Hui Zhen (LKK Auto)
Subject: RE: XE 3791U Surveyed by Steve (CS/CTI21011248/Euy3)

Dear Hui Zhen,

AUDIT CHECK DONE FOR XE3791U, FOUND NO LABOUR IN REPAIRER ESTIMATE.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Hui Zhen (LKK Auto)

Sent: Monday, 8 November, 2021 1:20 PM

To: Simon Ho (LKKAuto)

Subject: XE 3791U Surveyed by Steve (CS/CTI21011248/Euy3)

Dear Simon,

For your audit

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)