

Date: 30/10/2021
 Vehicle No: SMN3005P
 Model: HONDA VEZEL HYBRID
 Chassis: RU31217689-2016
 Reg.Year: 2019

Third Party Insurer: MS FIRST CAPITAL
 Third Party Veh No: SHB5675P
 Date of Accident: 30/10/2021
 Estimator: VICTOR
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		\$854.10
2	FRONT BONNET HINGE LH	1		\$53.50
3	FRONT BONNET HINGE RH	1		\$53.50
4	FRONT GRILLE OUTER GARNISH(CHROME)	1		\$437.60
5	FRONT GRILLE	1		\$374.70
6	FRONT GRILLE OUTER CHROME MOULDING LH	1		\$53.80
6	FRONT BUMPER	1		\$751.40
7	FRONT BUMPER SIDE BRACKET LH	1		\$23.90
8	FRONT BUMPER LOWER LIP	1		\$421.80
9	FRONT BUMPER LOWER GRILLE	1		\$84.20
10	FRONT BUMPER FOG LAMP LH	1		\$626.10
11	FRONT BUMPER FOG LAMP GARNISH COVER LH	1		\$65.10
12	FRONT BUMPER REINFORCEMENT	1		\$294.70
13	FRONT HEADLAMP LH	1		\$1,996.30
14	FRONT HEADLAMP LOWER BRACKET LH	1		\$34.20
15	FRONT FENDER LH	1		\$421.10
16	FRONT FENDER "HYBRID" EMBLEM LH	1		\$65.50
17	FRONT FENDER INNER SHIELD LH	1		\$125.90
18	FRONT WHEEL ARCH GARNISH COVER LH	1		\$178.90
19	FRONT DOOR LH	1		REPAIR
SUB TOTAL				\$6,916.30
LESS 20%				-\$1,383.26
PARTS TOTAL				\$5,533.04

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		\$50.00
2	FRONT FENDER INNER SHIELD CLIPS LH	1		\$40.00
3	FRONT WHEEL ARCH LH CLIPS	1		\$40.00
S/N TOTAL				\$130.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30/10/2021
Vehicle No: SMN3005P
Model: HONDA VEZEL HYBRID
Chassis: RU31217689-2016
Reg. Year: 2019

Third Party Insurer: MS FIRST CAPITAL
Third Party Veh No: SHB5675P
Date of Accident: 30/10/2021
Estimator: VICTOR
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. \$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT BUMPER LOWER LIP, FRONT FENDER LH, FRONT WHEEL ARCH COVER LH & ETC. \$1,000.00

TO DAIGNOSIS FAULT CODE & RESET MEMORY. \$120.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00

LABOUR TOTAL \$2,200.00

VIC	TOTAL	\$7,863.04
-----	-------	------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

