

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21011334/JEA3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0006136_01
Claimant Vehicle No : EZ1100S **Insured Vehicle No :** SKW8648C
 Date of Loss: 05/11/2021 Nature of Claim: TP Claim No: MPC2021D0004820

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EZ1100S**
 Make & Model: MERCEDES-BENZ C180K, 1.6 (A) Engine No: 27191031344416
 Reg. Date: 20/04/2011 (Man. Year: 2011) Chassis No: WDD2040452A524583
 Colour: Silver Odometer: 74362 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,901.50	3,681.42	220.08	5.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,115.00	1,470.00	645.00	30.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,016.50	5,151.42	865.08	14.38
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	6,016.50	4,100.00	1,916.50	31.85
+ GST 7.00/7.00% (S\$)	421.16	287.00	134.16	31.85
Nett Amount (S\$)	6,437.66	4,387.00	2,050.66	31.85
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		4,747.00		

INSPECTION

Date of Assignment: 09/11/2021
 Date Inspected: 09/11/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)
 Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2022)
Parts: 143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EZ1100S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Badly Dented	2,450.00 FL	*2,288.48 FL
2	1		*REAR RH FENDER (REPAIR)	Repair	0.00 FL	*- FL
3	1		*RH ROCKER PANEL GARNISH	Cut	630.00 FL	*615.00 FL
4	1		*REAR BUMPER (REPAIR) (NPA)	Repair	0.00 FL	*- FL
5	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	46.00 FL	*- FL
6	1		*REAR BUMPER SILENCER CHROME MOULDING	Necessary	125.00 FL	*125.00 FL
7	1		*DOOR CHROME MOULDING	Necessary	106.00 FL	*106.00 FL
8	1		*FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP (RUBBER)	Necessary	328.00 FL	*305.99 FL
10	1		*REAR DOOR MODULE BOX	Shorted	650.00 FL	*650.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,335.00	4,090.47
- List Item Discount on L Items 10.00/10.00% (\$\$)	433.50	409.05
Total Parts (\$\$)	3,901.50	3,681.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT	New	1,000.00	800.00
2	LABOUR CHARGE	New	780.00	550.00
3	WIRING	New	35.00	20.00
4	TRANSFER DOOR FITTING ETC	New	180.00	60.00
5	TUFF COATING	New	120.00	40.00
			Gross Labour Cost (\$)	2,115.00
				1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >