	ASSIGNATION	79/1/2015
rom: Date: 8/11/2021	Veh No: SKU230L Type M.Cab/ M.Cycle / Bus / Van / Lon	Yr Regn: 29/6/2015
Estimated Cost:		1771
DD I TP WS I TP RES I OD RES I EVA I INV I MV	: Truck / Trailer or	110/
To Inspect Vehicle No: SKU 230L	Make: Honda Vezel	AC: Insured / Std / NI / NA
	Colour Rod	
of 8 Kaki Bt Ne4 Premier # 01-49	Sp.Reading 26360	T/Radio: Insured / Std / NI / NA
	Eng/No: L15 B352167	3
Insured:	C/No: 2411821656	
Policy No.	Gen. Cond: Good / Fair / Foor / Burnt	
Claims No.	Steering: Iporder / Jammed / Leaked /	Burnt or
Sum Insured: Excess:	Brake: Igorder / Jammed / Leaked /	
(Client's Record)	Modi: NII / SEM / STD A/Rim or	
Make of Veh:	Tyre Size: F: 215/55/	17 BS
	R: 215/55/	U.P
(Policy Condition)	O/S OSIDUNIEXNOVAIGYIFSILIZAI	MIC / OHTSU / PT / SUMI /
Remark: The veh had commenced its repair at the time of inspection.	TOYO / YOKO or	
	Froni	Rear
Bal. or Market Value: 44,000/	R/Bal, A mm	R/Bal. 5 mm
IDAC Accident Rport: Consistent? : Yes or No	L/Bal. A mrn	L/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A. 5/11/2024	D.O.I. 8/11/2021
Est. Repairs: 10 days Res.: Yes or No	Survey held at Bi frest	A 1
Lum Sum: % 3 Val.: Yos or No	Des. of Damages : FR / For / O/S /	
CA / REV / REP. / 24 HRSWP		
Venice, in	The U/C / Chassis frame / Body	Structure affected due to collision.
Date / Time Action / Instruction Range 14000/2 - 15,	600/2	
		1
Recommended COR is L	5 \$ 14,250/2 TGUN	luc
	29/4/	2027
MV 44,000/2		11/11/2021
NV 18 398/2		191122
NV 18,398/2		
Dale/Time, File Pass to? : Prell. Report	Days Of Repair:	l. 5
i) : Final Report	Resurvey No. of Trip:	Survey Fee:
Date/Time, File Return to?	Id Fee: Site Insp. (\$ 1	Transportation:
2) Ad		_) _s+Rs,_si
	: Interview (\$	Photos
Represent:	: Tech. Invs (\$	_) Offices
Lump Sum/I.E.I: (%)	: Weellend (\$	
		TOTAL

AUTO PTE LTD

© KAKI BUKIT #01-49 SINGAORE 415875
4457
-65 64524584
≥g No: 201929175W

Vehicle number: Make and model: Chassis: SKU230L Honda Vezel RU1-1021656

	Chas	SIS: RU1-1021030
0.		List price 2015
Qty	Spare parts	List pitee
1	Tailgate	\$ 800.00 953.30 DDV
1	Tailgate "Vezel" emblem	\$ 56.50 NECV
1	Tailgate windscreen glasss upper rubber moulding	\$ \text{52.00}
1	Tailgate windscreen glass lower rubber moulding	\$ \sqrt{52.00} \ NEW
1	Tailgate windscreen glasss RH rubber moulding	\$ \sqrt{52.00}
1	Tailgate windscreen glass LH rubber moulding	\$ \sqrt{52.00}
1	Tailgate LH lamp	\$ 335.00 413.30 BRV
1	Tailgate LH lamp gasket	\$ /38.50 NECO
1	Tailgate RH lamp	\$ 335.00 413.30 BRV
1	Tailgate RH lamp gasket	\$ \(\sqrt{38.50} NELY \)
1	Tailgate outer garnish	\$ 231.00 BRV
1	Tailgate outer garnish emblem	\$ 28.00 NEW
1	Tailgate RH number plate lamp	\$ 55.10) (17)
1	Tailgate LH number plate lamp	\$ -55.10 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
1	Tailgate reverse camera	\$ 1,020.70- NDX
1	Tailgate inner trim board	\$ 154.70 BRV
1	Tailgate lock	\$ 180-20 189.00 JMV
1	Tailgate lock catch	\$ 27.50 NDX
1	Tailgate inner pull handle	\$ 28.60- NDX
1	Tailgate RH damper	\$ 182.00)
1	Tailgate LH damper	\$ -182.00 \ \\
1	Tailgate weatherstrip	\$ 96.80 TNV
1	Rear bumper	\$ \(\square \) 465.70 BR \(\square \)
1	Rear bumper lower cover	\$ 129.00 -250.00 BRV
1	Rear bumper LH reflector	\$ 75.00141.10 BRV
1	Rear bumper LH side cover	\$ \square 198.00 BR \square
1	Rear bumper LH side retainer	\$ \ \ 26.50 \ \ NECI/
1	Rear bumper RH side retainer	\$ 26.50
1	LH taillamp	\$ 385.00 487.60 BRV
1	LH taillamp gasket	\$ 20.00 44.20 NECV
1	RH taillamp	\$ 385.00 -487.60 BRV
1	RH taillamp gasket	\$ 20.00 44.20 NECV
1	End panel	\$ 382.70 415.60 DDV
1	End panel inner garnish	\$ / 109.00 BRV
1	End panel antenna sensor	\$ 65.10 BRU
1	End panel buzzer sensor	3 03.003
1	Rear compartment panel tray garnish	\$ 201-90 485.90 BRV
1	Rear compartment panel tray garnish top cover board	\$ 430.30 NDX

1	Rear LH fender	\$ \square 884.80 DDV
1	Rear LH fender arch moulding	\$ \square 198.00 BRV
-		s 145.90 NDX
1	Rear LH fender splash shield	\$ / 298.50 BRV
1	Rear LH fender inner trim board	\$ 45.30 NDV
- 1	Rear LH fender air vent	1 - (- (- (- (- (- (- (- (- (-
1	Rear RH fender	4 004.00 4
- 1	Rear RH fender arch moulding	\$ \ \ 198.00 \
1	Rear RH fender splash shield	\$ 145:90 NDX
1	Rear LH fender inner trim board	\$ \sqrt{298.50 BR}
1	Rear RH fender air vent	\$ 45.30 BR
1	Bonnet	\$ 892.30 NDX
1	Bonnet RH hinge	\$ 48.50 \ NDX
1	Bonnet LH hinge	\$ -48.50
- 1	Bonnet lock	s 98.00 ND2
1	Bonnet RH inner side rubber moulding	\$ 37.50
1	Bonnet LH inner side rubber moulding	\$ 37.50
1	Bonnet RH inner centre rubber moulding	\$ 23.00 \ ND \
1	Bonnet LH inner centre rubber moulding	\$ 23.00
1	Bonnet insulator	\$ 122.30
1	Front bumper	\$ 762.70 801.70 BR
1	Front bumper RH side retainer	\$ /22.80 NEC/
1	Front bumper LH side retainer	\$ 308.90 327.70 BR
1	Front bumper RH fog lamp	
1	Front bumper RH fog lamp bracket	
1	Front bumper RH fog lamp garnish	\$ 308.90 327.70 BR
1	Front bumper LH fog lamp	\$ 27.00 NDX
1	Front bumper LH fog lamp bracket	\$ 46.00 BR
1	Front bumper LH fog lamp garnish	\$ \(\sqrt{78.40} \) BR
1	Front bumper lower centre grille	\$ 229.40 381.00 BR
1	Front bumper lower spoiler Front bumper reinforcement	\$ 224 70 321.00 PD
1	Front bumper reinforcement RH top moulding	6 274.70 2000)
1	Front bumper reinforcement LH top moulding	\$ 38.00 \ NDX
1	Front bumper towing cover	\$ 17.10 NDY
1	Front grile	\$ 250.00 351.80 BR
1	Front grille emblem	\$ / 23.40 NEC
1	Front grille centre bracket	\$ 39.50 78.00 BRV
2	Front grille chrome moulding	\$ 153.80 196.00 BRV
1	Front grille outer cover	\$ 421.00 BR.
1	RH headlamp assy	5 174. TO 1705 50 BEV
1	RH headlamp lower bracket	\$ 33.90 42.00 }
1	RH headlamp side bracket	\$ 35.00
1	LH headlamp assy	\$ 1715, 10 1,795.50 BRV
1	LH headlamp lower bracket	\$ 38.90 42.00 BR
1	LH headlamp side bracket	\$ 35.00
1	Front horn (low tone)	\$ HO.50 ? NNX
1	Front horn (high tone)	\$ 110.50
1	Front outside temperature sensor	\$ 83.00 \ NDX
1	Front outside temperature sensor bracket	\$ 27.00
1	Front RH fender arch moulding	\$ 180.00 220.00 7 BB
1	Front LH fender arch moulding	\$ 180.00 220.00
1	Support panel	\$ 520.00 586.30 DDV
		220 00

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Supplementary

Vehicle No: Model and make: Honda Vezel

SKU230L

Qty Parts List price 2015 \$ 355.04 650.40 BRV RH rear door inner trim board RH rear door lock \$ 196.30 / 196.30 JMV LH rear door inner trim board \$ 355.00 -650.30 BRV \$ 196.30 / 196.30 JM/ LH rear door lock Rear bumper lower cover RPT X 251.00 BR 226.40 BR Rear compartment tool sponge tray 517.70 700.20 DDV Exhaust silencer Exhaust silencer gasket 140.50 NECV 40.50 2,911.40 -20% S 582.28 2,329.12 Parts Qty Special nett price 1set RH rear door inner trim board clips 60.00 NEU 30.00 1set LH rear door inner trim board clips 30:00 Rear bumper chrome step moulding 380:00 DD \$ 250.00 End panel chrome moulding 1250.00 DD V Labour

Resurvey 9/11/2022 Talin Im 1630/115

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis

Remove and replace exhaust silencer and gasket to assist repair

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Final amount: \$

\$

3,199.12

120.00 NN

		•		1,376.60
	Radiator	\$		31.80
	Radiator RH side guide	9		31.80 Y ND
	Radiator LH side guide	9		-568:30
1	Aircon condenser	9		127.80
1	Air duct	2		127.00
		•		23,441.40
		9		4,688.28
	-20)% \$		18,753.12
		2		18,733.12
			Canadal nat	t price
Qty	Spare parts	-	Special net	t price
				100.00 NNX
lset	Bonnet insulator clips	\$		100.00 NEW
1set	Front bumper clips	\$	39100	80.00 N NX
lset	Front RH fender splash shield clips	9		-80:00 NNX
lset	Front RH fender arch moulding clips	2		80.00 NNX
1 set	Front LH fender splash shield clips	\$		80.00 W NT
1set	Front LH fender arch moulding clips	2		70.00 NECV
1 set	Front grille clips	\$	30-00	-90.00 NNX
1	Radiator coolant	\$	20,00	70.00 BE
1	Front number plate	2	3000	
1	Tailgate windscreen glass sealant	9	30,00	-80.00 } NECV
1	Tailgate windscreen glass inner seal	. 3	400	80.00 NEC
1 set	Tailgate inner trim board clips	9	30100	70.00 NEC
1 set	Tailgate outer garnsih clips	9	30:00	-100.00 NECV
lset	Rear bumper clips	3	30.00	320.00
1set	Rear bumper reverse sensors	2	200,00	
lset	Rear fender RH arch moulding clips	2	30'00	-80.00 } NEW
lset	Rear fender LH arch moulding clips	9	50· N	-80.00 NEW
1	Rear fender RH scalant	9	30,00	90.00
lset	Rear fender RH inner trim board clips	9	30.00	-80.00 NEW
lset	Rear fender LH inner trim board clips	\$	30.00	-80:00 J
1	Rear fender LH sealant	\$		-80.00 NNX
1	Rear number plate	\$		70:00 NNX
1	End panel	\$	200	50.00 N€C
lset	End panel inner garnish clips	.5	30.00	90.00 NCC
(FRO	NT PORTION)			
	ir charges to remove, check, replace and reinstall damages bodyparts.	\$	400:00	1,000.00
	nel beating, cut / weld and re-align all affected panels			
Spray	painting on affected panels	\$	400.00	-900.00
				100
Check	wiring and lighting system	\$		70.00 NNX
Apply	rust coating chemical on affected panels	\$		40.00-NN X
Remo	we and replace aircon condenser, pipes and hoses to assist repair. To refill aircon gas	\$		250.00-)
				FNAT
Remo	we and replace radiator assy, pipes and fan assy to assist repair. To refill coolant	\$		250.00

Refocus and adjust headlamps assy	\$	-60.00 WN
(RERR PORTION) Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$	100000 +,600.00
Spray painting on affected panels	\$	1000,00 1,400.00
Check wiring and lighting system	\$	-100.00 NNX
Apply rust coating chemical on affected panels	\$	KNN 00.08
Remove and replace tailgate windscreen glass to assist repair	\$	120,00 250.00
Remove and replace tailgate inner components to assist repair	\$	80400 180.00
Remove and replace tailgate reverse camera to assist repair	\$	100.00- NNX
Remove and replace rear bumper reverse sensors to assist repair	\$	60:00 100.00/
Remove and replace rear inner trims, garnish and boards to assist repair	\$	80°00 220.00 /
Remove and reinstall petrol tank, pipes and hoses to sensors to assist repair	\$	150.00 NNX
Remove and reinstall roof lining, seats and carpet to assist repair	\$	380.00 NNX
Survey Regurey		
8/11/2021 7/11/2021 Torin lin	Total: \$	28,003.12
1430 hrs	Pauts.	13484.80
		1190.00
Lump sum repair	Labour	3140,00
Repair days 10	@ 20%	17814.80 3562.96
		14,251.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 14,250/2

Talin hun 29/4/2022

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	540D
Vehicle No.:	SKU230L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Apr 2022
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.55 AUTO
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L15B3521673
Chassis No.:	RU11021656
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,463.00
Original Registration Date:	29 Jun 2015
First Registration Date:	29 Jun 2015
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$9,463.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2025
PARF Rebate Amount: Intended COE Rebate Details	\$6,150.00
COE Expiry Date:	28 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$19,452.00
Total Rebate Amount:	\$25,602.00

The information contained herein is correct as at 20 Apr 2022

ОК

MV 44,000fx PV 25,602/x NV 18,398/2

76/1 lin lin 20/4/2022





Honda Vezel 1.5A X

\$50,800

\$13,210 /yr

21-Oct-2015

102,688 km

Available SAN

\$0 Driveaway Available. Immediate Approval, In House And Bank Loan Available, Trade In Welcome Call Our Friendly Representatives For More Information Or For A Viewing Of The Car.

PROMISE AN

AL Autocar Pte Ltd.

Honda Vezel 1.5A X

Posted: 15-Apr-2022

\$49,000

\$13,060 /vr

23-Sep-2015

1,496 cc

120,000 km

SUV Available

Headunit Will Be Replaced! 1 Owner! Original Honda Modulo Bodykit! No PHV Usage. 100% Guaranteed! New Tyres! 100% Loan Available, Very Reliable And Fuel Efficient 1 Owner Car, Low Maintenance And Low Monthly Repayment Trade In Welcomel Flexible Ban

CONSTRUMENT

Posted: 22-Peb-2022



Honda Vezel 1.5A X

\$45,800

\$12,170 /yr

18-Sep-2015

1,496 cc

SUV

Available

Accident Free, Well Maintained, Superb Condition, Spacious Interior, Low Fuel Consumption, STA/VICOM Evaluation Welcome, Flexible Loan Available! Bank And In House Loan Available! No Gimmicks! Trade In Welcome! Best Value For Money Drive! Don't Miss It, Contact.

This car comes with 6-mth sgCarMart Warranty - the best protection for your car, Learn More

Posted: 31-Mar-2022



Spruce up your car for 2022

We will soon be approaching a new year. Want to change a lucky colour for your car to enhance your luck in the year 2022? Find your preferred spray paint workshop to customise your unique colour.

Find out more!

ADVERTISING





Honda Vezel 1.5A S

\$46,800

\$13,250 AT

22-Jun-2015

1.496 cc

27,000 km

SIN

Available

PREMIUM AD

Definitely Your Choice Of SUV For Short Term! Wear & Tear Replaced Accordingly, Well Taken Care By Previous Owner, Previous Owner Upgraded To MPV With Us. Attractive Interest From 1.88%! Warranty & Servicing Can Be Arranged For Peace Of Mind! New Coated Paint.

SG Car Choice Pte Ltd

Posted: 09-Apr-2022



Honda Vezel 1.5A X

\$42,800

\$12,750 /vr Rare Gem, Elegant Mica Silver Vezel 1.5A With Nice Red Leather Seats. Genuine Low Mileage Done 97581km! Totally Good As New, Test Drive/See To Certify, Fussy Car Lover Owner, Nice Car Number, New Paintwork, Road Tax Till Jun 22, 100% Accident Free, In House High.

18-Jun-2015

1,496 cc

97,581 km

SUV

Available

PREMIUM AR

Lake View Credit Pte Ltd

Posted: 17-Apr-2022



Honda Vezel 1.5A X

\$42,000

\$13,200 /yr

17-Apr-2015

1,496 cc

67,000 km

SUV

Available

PREMIUM AD

Reliable And Best Compact SUV For Cat A Category! Spacious Interior And Huge Boot Compartment! Good Driving Agility! Welcome STA Evaluation For A Piece Of Mind! Flexible Financing Schemes And In House 100% Loan Available, Low Interest Rate, High Trade In, Conta,

Monster Motors Pte Ltd

Posted: 22-Feb-2022



Honda Vezel 1.5A X

\$41,000

\$12,880 /yr Owner 2nd Car. Genuine Low Mileage, Non PHV Unit, Low Fuel Consumption, Reliable, Immaculate Condition And Very Well Maintained.

Test Drive To Believe It! Best Compact SUV For Cat A Category!. Easy Maintenance, Popular Japanese SUV, With Spacious Interior And H.

06-Mar-2015

1,496 cc

75,000 km

SUV

Available

DIRECT OWNER

Posted: 09-Apr-2022

1.5A X Honda

\$42,800

\$13,430 /vr

25-Feb-2015

1.496 cc

103,200 km

Available



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/11/2021 17:55 (SGT) Date of Accident 05/11/2021 20:20 (SGT) Exact Location of Accident PIE, Singapore Additional Location Information PIE TUAS BEFORE STEVENS ROAD EXIT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKU230L

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LOO SHIAN CHYN NRIC No SXXXX540D Email Address SCOTCHHERE123@GMAIL.COM Mobile Phone No (Phone) +65-97608627 Alternative Phone No (Home) +65-97608627

VEHICLE PARTICULARS

Manufacturer Honda Model Vezel Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Auto

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd Type of Coverage Comprehensive Fleet Policy Policy Number SI21V12439/VPE/R00 Cover Note Number

DRIVER

Name of Driver LOO SHIAN CHYN NRIC No SXXXX540D

Date Of Birth 09/08/1964 Occupation Indoor Date Of Driving Pass 30/05/1992 Driving experience 29 YEARS AND 6 MONTHS Gender Male Mobile Number (Phone) +65-97608627 Alt. Phone Number (Home) +65-97608627 Email Address SCOTCHHERE123@GMAIL.COM Address APT BLK 836 JURONG WEST ST 81 #06-65 Address complement Postcode 640836 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name TEO KOK LEOW Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SMA6737J Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Private car

Vehicle Category

Name of Driver	-
Contact Number	2
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

SLD7366K - -
-
-
- 1
Private car
-
-
-
-
-
-
-
-
-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TEO KOK LEOW
Gender	
Phone No	
Address	
Address Complement	-
Post Code	
Approximate Age Years Old	
Injuries Sustained	
Injured person in which vehicle?	SKU230L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	No
INJURED 2	
Name of injured person	LOO SHIAN CHYN
Gender	
Phone No	-
Address	-
Address Complement	-
Post Code	
Approximate Age Years Old	
Injuries Sustained	-
Injured person in which vehicle?	SKU230L
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Trate

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A = SEU230 L B = BNIZ = B C = SLD = 366 E

B 7 x A 7 x C 7 >

NE CANDEL

	be Circumstances of the Accident
	On 5 Nov 2021, around 8-20pm. I was traveling at lone 2 (1
8	and met an accident at (PIE) before Steven Ad.
	The car (SLD 7366K) in front of me sudden e-bate 1
	I mange to stop in time, However the Valide bet (SMA6737
	Betind did not and bang onto my Vehicle (SKU230L).
_	Rear portion pretty body. Dix to the impact , my
	Vehicle bring out the front Vehicle.
	You can refer to the accident photos for more information.
1	
_	
-	

Declaration

I'We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel