

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

* Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) _ S + RS. _ SI

) Photos


) Others

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



7/11/24 2/s \$1000 confirmed with Dand

2024 until 19-10-2024 17958925

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT,
#05-68 (S737869)

not Admitted
new
18/11/21
2/5 \$1000
whichever Attorney
3 days.

TO : SOMPO DATE : 18-Nov-21
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
VEHICLE DETAILS
VEHICLE NO : SJT5719D
MODEL : HYUNDAI AVANTE
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER 478.50 cur/70.11	1	\$ 715.40	\$ 715.40
2	FRONT BUMPER SIDE RETAINER 29 0/5 cur	2	\$ 65.90	\$ 131.80
3	FRONT BUMPER LOWER CENTRE GRILLE 11	1	\$ 212.00	\$ 212.00
4	HEADLAMP RH 11	1	\$ 846.70	\$ 846.70
5	FRONT FENDER RH 12	1	\$ 696.20	\$ 696.20
6	FRONT FENDER EMBLEM "VVT" 25.00 new	1	\$ 34.50	\$ 34.50
7	FRONT FENDER INNER SHIELD RH 11	1	\$ 142.90	\$ 142.90
8	FRONT FENDER MUDFLAP RH 11	1	\$ 156.10	\$ 156.10
9	FRONT KNUCKLE ARM 11	1	\$ 441.50	\$ 441.50
10	FRONT WHEEL HUB BEARING 11	1	\$ 185.70	\$ 185.70
11	FRONT LOWER ARM 11	1	\$ 385.40	\$ 385.40

TOTAL PRICE 207 \$ 3,948.20
LESS 10% \$ 394.82
SUB TOTAL PRICE \$ 3,553.38

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP SET new	1	\$ 65.00	\$ 65.00
2	FRONT FENDER INNER SHIELD RH CLIP SET 11	1	\$ 70.00	\$ 70.00
4	FRONT SPORTS RIM RH 11	1	\$ 850.00	\$ 850.00
5	FRONT TYRE RH 11	1	\$ 280.00	\$ 280.00

TOTAL \$ 1,265.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	CUT OFF AND REPLACE REAR RHS FENDER AND SIDE SILL PANEL. RESTRUCTURE SIDE CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.	\$600.00		380
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$600.00		400
3	ADJUST AND FOCUS FRONT LED LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$80.00		20
4	DISMANTLE AND REPLACE FRONT RHS UNDER-CARRIAGE COMPONENT.	\$200.00		11 X
5	WHEEL ALIGNMENT.	\$150.00		11 X

TOTAL

\$1,630.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,818.38
TOTAL LABOUR COST : \$ 1,630.00
TOTAL REPAIR COST : \$ 6,448.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-532-50
202
P-426
S.N-45
L-800
1271
202
1016