

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	📄	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref: CS/EQI21011355/Atf3		
5 MAXWELL ROAD		Date: 08/11/2021		
#17-00 TOWER BLOCK				
MND COMPLEXSINGAPORE 069110		Code: EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 4077T	Veh. Inspected	SML 3493Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM21HO01653-JT	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	08/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/11/2021	Inspection Date	09/11/2021	
Survey held at	23 Kaki Bukit Avenue 4, #04-01			
Repairer	ADVANCE AUTO GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				