

08th Nov 2021

Quotation No.: Q21-OPS-1589

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
By email : mt_claim@lonpac.com

Attn: Claims Department

Dear Sir/Mdm

Estimated Cost of Repair job for SBS6437K Accident on 28/10/2021 @ Near 474 Pasir Ris Drive 6, Block 474, Singapore 510474 involving YP8668R

S/N	Description	Qty.	Unit Price	Total Price
1	Supply labour to replace front RHS rear view mirror	1 day	\$200.00	\$200.00
2	RHS REAR VIEW MIRROR ✓ BR	1 PC	\$1,969.12	\$1,969.12
3	TRIANGLE STICKER ✓ NEC 20(SN)	1 PC	\$50.00	\$50.00
Part Disc -10% 1772.21				Total \$2,219.12
				7% G.S.T. \$155.34
				Grand Total \$2,374.46

Terms and Conditions:

Payment Terms : 30 days upon invoice
Quotation Validity : 30 days
Lead-Time : 1 working days
Price quoted subject to 7% GST

1892.21

Guo Qiang - LKK

09/11/2021

1 Day


P/P

Yours faithfully

TEN YONG SHUN

TEN YONG SHUN
ASSISTANT OPERATION MANAGER

Approval by



LexBuild Motors Pte. Ltd.

11 Tuas Bay Close, #04-01/02 WEST STAR, Singapore 636996
Tel: (65) 6456 3533, Fax: (65) 6456 3353
Website: www.LexBuild.com, Email: operations@LexBuild.com
ROC / CR GST Reg. No 201736397R

