

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref:	CS/SMR21011360/Bvf3e2	
	60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Date:	23/03/2022	
			Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 711B	Veh. Inspected	SMY 4250H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	TAX/10/21/2060	Excess (\$)	0.00	
	Assign From	HUA YEN	Assign Date	08/11/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	KMHD841CMJU725827	Colour	RED	
	Odometer	31305 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	5 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/10/2021	Inspection Date	08/11/2021	
	Survey held at	TEAM AUTOPRO PTE LTD			
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			