

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SMY 4250 H**

Model : **Hyundai Elantra**

Year : **2018**

Chassis No : **KMHD841CMJU725827**

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front bumper	1	\$ 874.40	\$ 874.40 574.00
2	Front bumper side retainer	2	\$ 39.80	\$ 79.60 70.00
3	Front bumper inner sponge	1	\$ 110.70	\$ 110.70
4	Front bumper reinforcement	1	\$ 695.80	\$ 695.80
5	Front bumper fog lamp	2	\$ 265.10	\$ 530.20
6	Front bumper fog lamp garnish LH 1	2	\$ 115.40	\$ 230.80 115.40
7	Front bumper licence plate	1	\$ 41.40	\$ 41.40
8	Front support panel	1	\$ 949.30	\$ 949.30
9	Front support panel top garnish	1	\$ 74.10	\$ 74.10
10	Headlamp LH 1	2	\$ 1198.00 1,698.80	\$ 3,397.60 1198.00
11	Headlamp lower bracket	2	\$ 128.00	\$ 256.00
12	A/c condenser	1	\$ 845.10	\$ 845.10
13	Radiator	1	\$ 710.50	\$ 710.50

Parts Sub Total : \$1357.40 8,795.50

20%

Discount :

\$ 391.48 1,759.10

PARTS TOTAL : \$1565.92 7,036.40

CRAN
NECV
NSX
DDXR
NDX
BRV
NDX
NDX
BRV
NSX
NDX

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Front bumper clips	1	\$ 50.00	\$ 30.00 50.00
3	Front bumper lower lip	1	\$ 780.00	\$ 780.00
4	Front bumper lower lip clips	1	\$ 50.00	\$ 50.00
5	Front bumper grille	1	\$ 850.00	\$ 569.00 850.00
6	Front bumper grille clips	1	\$ 50.00	\$ 50.00
7	Front bumper fog lamp garnish clips	2	\$ 50.00	\$ 30.00 100.00
8	Wrap sticker * provide invoice	1	\$ 900.00	\$ * * nec 900.00
9	Wrap protection sticker (3M) * provide invoice	1	\$ 1,200.00	\$ * * 1,200.00
10	Front support panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00
11	Front number plate w/casing	1	\$ 80.00	\$ 80.00
12	A/c fluid	1	\$ 80.00	\$ 80.00
13	Radiator coolant	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 4,350.00

Nos.	LABOUR	S\$
1	R&R a/c condenser	\$ 150.00
2	R&R radiator	\$ 150.00
3	Check wiring	\$ 20.00 100.00
4	Upholstery	\$ 200.00
5	Panel beating	\$ 400.00 1,000.00
6	Rust proofing	\$ 200.00
7	Spray painting	\$ 400.00 1,000.00
LABOUR TOTAL :		\$ 2,800.00

Survey Resurvey Lump sum repair
8/11/2021 9/14/2021 Repair days 4

1825 hrs 1540 hrs

11:00 AM 10:00 AM

PARTS TOTAL : \$ 7,036.40
SPECIAL NETT TOTAL : \$ 4,350.00
LABOUR TOTAL : \$ 2,800.00
GRAND TOTAL : \$ 14,186.40

* To provide invoices in order
to avoid recommended work

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Parts 1565.92
SN 659.60
Labour 820.60
4844.92
@ 20% 968.98
3875.94

LS 3850/2

TGrim 11/11
9/12/2021



VISIONWORKZ PERFORMANCE

Showroom / Workshop: Block 176, Sin Ming Drive, #03-01, Sin Ming Autocare, Singapore 575721
Website: www.visionworkz.com.sg Email: enquiries@visionworkz.com.sg
Company Registration No. 53016980X

INVOICE NO: TeamAutoProPteLtd/November/2021/001

COMPANY NAME: TEAM AUTO PRO PTE LTD

DATE: 16-11-2021

DATE	VEHICLE / VEHICLE NO:	JOB DESCRIPTION	REQUEST BY	PRICE
16-11	Hyundai Elentra SMY4250H	Accident Replacement Front Bumper Full Wrap Matt Black with 3M Matt Paint Protection Film and Matt Chrome Line Trimming Inclusive of Labour	Eric	\$1800.00
Thank You For Your Business!				\$1800.00

ISSUED BY: JAM

SIGNATURE: 

DATE: 16-11-2021



VISIONWORKZ PERFORMANCE

www.visionworkz.com.sg

Block 176, Sin Ming Drive,

Sin Ming Autocare, #03-01, S575721

Hp: 9828 2826 / 9843 1315