

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-35/36 S(737869)
Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd
Date: 03/11/2021
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLL3050E
CHASSIS NO: RU3123989
MAKE / MODEL: Honda Vezel 1.5 X CVT
DATE OF ACCIDENT: 02/11/2021
YOUR INSURED VEHICLE NUMBER: GBC8146X
MILEAGE: 367107 km

Steve (LKK)
9/11/21 3.00pm
WL AL
L/S
My AL
4 days

PARTS DeSCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 Rear tailgate — 00 ? X nn	1PC	\$ 1,450.00	\$ 1,450.00 953 ✓
2 Rear end panel — 1 X nn	1PC	\$ 830.00	\$ 830.00 X
3 Rear end panel top garnish — 1 X nn	1PC	\$ 155.00	\$ 155.00 X
4 Rear bumper — 00	1PC	\$ 955.00	\$ 955.00 762 ✓
		LIST TOTAL S\$:	\$ 3,390.00
		20.00% DISCOUNT S\$:	\$ 678.00
			\$ 2,712.00

1715
-20%
1372

SPECIAL NETT

1 Rear bumper clips — npc ? X nn	1 SET	\$ 80.00 30 ✓
2 End panel top garnish clips — 1 X nn	1 SET	\$ 80.00 X
3 Reverse sensor — shorted	1PC	\$ 490.00 200 ✓
	Special Nett Total S\$:	\$ 650.00 730

LABOUR CHARGES

1 To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts	\$ 900.00 400
2 To respray rear talgate, end panel and spare tyre panel	\$ 600.00 440
3 To remove and install rear tailgate glass	\$ 160.00 120
	LABOUR TOTAL S\$: \$ 1,660.00
	TOTAL S\$: \$ 5,022.00
	7% GST \$ 351.54
	GRAND TOTAL S\$: \$ 5,373.54

960
=2562
L/S-2049-60
=2050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: