



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS3/FCI21010359/Vvf3e2-1	
			Date: 12/11/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 1049J	Veh. Inspected	SMY 6209R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21002807MFCV	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	09/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 5008	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF30E9HD8FS179624	Colour	GREY	
Odometer	156328 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	GOODYEAR	7 mm	
L/H Front Tyre	215/55 R16	GOODYEAR	7 mm	
R/H Rear Tyre	215/55 R16	GOODYEAR	7 mm	
L/H Rear Tyre	215/55 R16	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2021	Inspection Date	12/10/2021	
Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES BLK 3022A UBI ROAD 1 #01-53 . SINGAPORE 408716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	