

BETHLEHEM AUTO

Page 1/2

ATTN : Budget Direct Insurance Singapore
(Auto & General Insurance (Singapore) Pte Ltd)

DATE : November 8, 2021
VEHICLE NO : GBK5480H
MODEL : Toyota Dyna
ACCIDENT DATE : November 2, 2021
TYPE OF CLAIM : TPPD
CLAIM ADVISOR :
EMAIL : claimsbethlehemauto@gmail.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
Rear Tailgate X Repair	1	\$ 1,675.06
Rear Taillamp RH X N/A	1	\$ 294.77
Rear Support Corner RH	1	\$ 194.71 119.3
Rear Side Gate Support Bracket RH - GBT	1	\$ 165.65 68.5
Rear Gate Hinge	2 1	\$ 291.98 76
Side Body Panel Gate RH X Repair	1	Repair
Total :		\$ 2,622.17 263.8
Discount 25% :		\$ (655.54)
		\$ 1,966.63 197.85

SPECIAL NETT	QTY	LIST PRICE
Rear Parking Sensor X N/A	1	\$ 280.00
Rear Sticker - 70KM - NBL	1	\$ 20.00 10
		\$ 300.00

LABOUR	QTY	LIST PRICE
Labour For Facilitate Repair		\$ 600.00 400
To Respray Affected Areas		\$ 600.00 400
To Check And Reconnect All Necessary Wiring		\$ 80.00 X
To Remove & Refit Cargo Cabin Reinforcement Plate		\$ 350.00 X
Rust Proofing		\$ 80.00 X
Sundaries		\$ 50.00 X
		\$ 1,760.00

1007.85

-20%: 800

Total Amount : \$

4,026.63

4 Days

4/5.

After repair photos.

Car. Q. up

11/11/21

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work to be resurveyed and is subject to confirmation by Insurance Company

Acknowledged by:

Sig:

1