

BETHLEHEM AUTO

Page 1/2

ATTN : Budget Direct Insurance Singapore
(Auto & General Insurance (Singapore) Pte Ltd)

DATE :

November 8, 2021

VEHICLE NO :

GBK5480H

MODEL :

Toyota Dyna

ACCIDENT DATE :

November 2, 2021

TYPE OF CLAIM :

TPPD

CLAIM ADVISOR :

EMAIL :

claimsbethlehemauto@gmail.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
Rear Tailgate X Repair	1	\$ 1,675.06
Rear Taillamp RH X N/A	1	\$ 294.77
Rear Support Corner RH	1	\$ 194.71
Rear Side Gate Support Bracket RH - GBT	1	\$ 165.65
Rear Gate Hinge	2	\$ 291.98
Side Body Panel Gate RH X Repair	1	Repair
Total :		\$ 2,622.17
Discount 25% :		\$ (655.54)
		\$ 1,966.63

SPECIAL NETT	QTY	LIST PRICE
Rear Parking Sensor X N/A	1	\$ 280.00
Rear Sticker - 70KM - MBL	1	\$ 20.00
		\$ 300.00

LABOUR	QTY	LIST PRICE
Labour For Facilitate Repair		\$ 600.00 400
To Respray Affected Areas		\$ 600.00 400
To Check And Reconnect All Necessary Wiring		\$ 80.00 X
To Remove & Refit Cargo Cabin Reinforcement Plate		\$ 350.00 X
Rust Proofing		\$ 80.00 X
Sundaries		\$ 50.00 X
		\$ 1,760.00

4 Days

4/5.

After repair photos.

Car. Q. up

11/11/21

Total Amount :

\$

4,026.63

ALL Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work to be resurveyed and is subject to confirmation by Insurance Company

Acknowledged by:

Sig:
