



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: HELENA TAN

Ref: CS/INC21011415/Atf3e2
Date: 16/12/2021
Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 4307D	Veh. Inspected	SLR 8012B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1150370-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	09/11/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NRE1610022289	Colour	BROWN
Odometer	89820 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	HABILEAD	6 mm
L/H Front Tyre	195/65 R15	HABILEAD	6 mm
R/H Rear Tyre	195/65 R15	HABILEAD	6 mm
L/H Rear Tyre	195/65 R15	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/11/2021	Inspect Date / Time	09/11/2021 (11:54 AM)
Survey held at	F-1 AUTOCLINIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------