



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21008475/Gucn2-1	
			Date: 26/11/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9157C	Veh. Inspected	SMS 8181D	
Policy No.	DMCVSNA00088702000	Coverage (\$)	0.00	
Claim No.	SNM21D204439/C02	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	08/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES-BENZ S320L	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2221622A398678	Colour	BLACK	
Odometer	39210 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 ZR20	FALKEN	6 mm	
L/H Front Tyre	245/40 ZR20	FALKEN	6 mm	
R/H Rear Tyre	245/40 ZR20	FALKEN	6 mm	
L/H Rear Tyre	245/40 ZR20	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/08/2021	Inspection Date	13/08/2021	
Survey held at	A S AUTO SERVICE NO 1 KAKI BUKIT #01-106 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	