

FW: ESTIMATE FOR SLU9923A**Rasul (LKKAuto)**

Mon 10/1/2022 5:46 PM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Case finalised

Best Regards,

Rasul | Assessor**LKK Auto Consultants Pte Ltd**Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*Save the Earth. Print only when necessary.***From:** info@ktauto.com.sg [mailto:info@ktauto.com.sg]**Sent:** Friday, 7 January, 2022 2:25 PM**To:** Rasul (LKKAuto)**Subject:** RE: ESTIMATE FOR SLU9923A

please close as per your finalise, LOD to me sent over to your side?

From: "Rasul (LKKAuto)" <Rasul@lkkauto.com>**Sent:** 1/4/22 3:43 PM**To:** "info@ktauto.com.sg" <info@ktauto.com.sg>**Subject:** RE: ESTIMATE FOR SLU9923AHi Wendy,

No photo we unable to accept it

Best Regards,

Rasul | Assessor**LKK Auto Consultants Pte Ltd**Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: info@ktauto.com.sg [<mailto:info@ktauto.com.sg>]

Sent: Tuesday, 4 January, 2022 10:41 AM

To: Rasul (LKKAuto)

Subject: RE: ESTIMATE FOR SLU9923A

sorry we did not take any photos

From: "Rasul (LKKAuto)" <Rasul@lkkauto.com>

Sent: 12/27/21 1:21 PM

To: "info@ktauto.com.sg" <info@ktauto.com.sg>

Subject: RE: ESTIMATE FOR SLU9923A

Hi Wendy,

Kindly forward to me the damage photo for the front bumper cover?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: info@ktauto.com.sg [<mailto:info@ktauto.com.sg>]
Sent: Monday, 27 December, 2021 12:28 PM
To: Rasul (LKKAuto)
Subject: RE: ESTIMATE FOR SLU9923A

the invoice is for SLU9923A, YOU CAN CHECK THE SPARE PART NUMBER, SUPPLIER'S INV DOES NOT HAVE CAR PLATE NUMBER FIELD.

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

From: "Rasul (LKKAuto)" <Rasul@lkkauto.com>
Sent: 12/21/21 10:10 AM
To: "info@ktauto.com.sg" <info@ktauto.com.sg>
Subject: RE: ESTIMATE FOR SLU9923A

[Hi Wendy,](#)

Invoice didn't show vehicle number

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: info@ktauto.com.sg [<mailto:info@ktauto.com.sg>]

Sent: Monday, 20 December, 2021 2:43 PM

To: Rasul (LKKAuto)

Subject: RE: ESTIMATE FOR SLU9923A

Pls refer to the inv attached, front bumper cover changed

Yours faithfully

Wendy Siew

On and behalf of

Kian Teong Auto Centre

176 Sin Ming Drive

Sin Ming autocare #01-08

Singapore 575721

Tel: 65 64556268

Fax: 65 64555166

HP: 91786498

Website: www.ktauto.com.sg

From: "Rasul (LKKAuto)" <Rasul@lkkauto.com>

Sent: 12/20/21 12:47 PM

To: "info@ktauto.com.sg" <info@ktauto.com.sg>

Subject: RE: ESTIMATE FOR SLU9923A

Hi Wendy,

Refer to attachment

Audit checked parts prices is high, necessary adjustment has to be made.

Finalised amount is \$ 2,850 / 4 days of lump sum repair

Kindly confirm and revert back

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: info@ktauto.com.sg [<mailto:info@ktauto.com.sg>]

Sent: Thursday, 9 December, 2021 11:38 AM

To: Rasul (LKKAuto)

Subject: ESTIMATE FOR SLU9923A

Please assist to finalise estimate ASAP

Yours faithfully

Wendy Siew

On and behalf of

Kian Teong Auto Centre

176 Sin Ming Drive

Sin Ming autocare #01-08

Singapore 575721

Tel: 65 64556268

Fax: 65 64555166

HP: 91786498

Website: www.ktauto.com.sg