



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0904/2021/JT
DATE : 3-Nov-21
WIP : 51849

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 08/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days exclude 1 Sunday

Johnny Boo 20 Dec 21

OWNER'S NAME : MS AMANDA KOH TING TING
ADDRESS : 53A TAVISTOCK AVENUE
SINGAPORE 554351
TELEPHONE : HP +65 96992335
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900249336
VEHICLE NO : **SMW 820 A**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 25/11/2019
ENGINE NO : CHZ C31378
CHASSIS NO : WAUZZZ8V1KA101933
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Nov-21
PLACE OF ACCIDENT : CTE (CITY) BEFORE HAVELOCK EXIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 820 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND REISNTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	\$ 280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELETRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	480.00	
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,550.00	\$ 1,000.00
5	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING, LHS REAR FENDER AND SPRAE WHEEL HOUSING.	\$	4,500.00	\$ 1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,282.00	\$ 2,852.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 820 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,944.00	\$ 1,555.20
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	
3	REAR BUMPER ADAPTER - LH	1	\$ 38.00	
4	REAR BUMPER TOP GUIDE SECTION - LH / RH	2	\$ 32.00	
5	REAR BUMPER LOCKING MECHANISM	2	\$ 59.00	
6	REAR BUMPER SPOILER	1	\$ 237.00	\$ 189.60
7	REAR LIGHT REFLECTOR - LH	1	\$ 41.00	\$ 32.56
8	REAR TAIL LIGHT - INNER / OUTER	2	\$ 1,754.00	\$ 1,403.20
9	REAR TAIL LIGHT TRIM - LH / RH	2	\$ 60.00	
10	REAR BUMPER REINFORCEMENT	1	\$ 603.00	
11	REAR BUMPER BRACKET - LH / RH	2	\$ 56.00	
12	REAR BUMPER GUIDE SECTION - LH	1	\$ 67.00	
13	REAR PARKING AID SENSOR	2	TBC	\$ 195.12
14	REAR LID	1	\$ 3,404.00	\$ 2,723.20
15	REAR LID ATTACHEMENT PARTS	1	\$ 295.00	
16	REAR LID GASKET	1	\$ 205.00	\$ 164.00
17	ADHESIVE	1	\$ 19.00	\$ 14.88
18	AUDI EMBLEM	1	\$ 138.00	\$ 110.00
19	A3 EMBLEM	1	\$ 99.00	\$ 79.04
20	REAR END PANEL	1	\$ 360.00	
SUB TOTAL SPARE PARTS		:	\$ 9,604.00	\$ 6,466.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.


55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 820 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
				\$ 6,466.80
21	REAR END PANEL REINFORCEMENT	1	\$ 733.00	
22	REAR END PANEL CONNECTING PLATE - LH / RH	2	\$ 290.00	
23	REAR NO PLATE	S/N	\$ 60.00	
24	A / SEALANT	S/N	\$ 180.00	
25	C / WAX	S/N	\$ 140.00	
26	METAL FILLER POWDER	S/N	\$ 280.00	
27	STONE CHIP	S/N	\$ 180.00	
28	SUNDRIES		\$ 350.00	\$ 3.60
TOTAL SPARE PARTS		:	\$ 11,817.00	\$ 6,470.40
TOTAL LABOUR CHARGES		:	\$ 10,282.00	\$ 2,852.00
GRAND TOTAL		:	\$ 22,099.00	\$ 9,322.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT