



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CS/CTI21011445/Uvy3
3 ANSON ROAD #16-00		Date:	09/11/2021
SPRINGLEAF TOWERSINGAPORE 079909		Code:	CTI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 4867U	Veh. Inspected	Q 69M
Policy No.	DMCVSNW00040282100	Coverage (\$)	0.00
Claim No.	SNM21D206422/C02/YN4867U/lewlc	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	09/11/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/10/2021	Inspection Date	09/11/2021
Survey held at	15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ CENTRE		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			