



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|---|--------------------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: OH VALE | | Ref: CS/ASM21011449/Kuy3e2 Date: 19/11/2021 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHA 5081H | Veh. Inspected | SLL 1255U |
| Policy No. | VFX/P2419138 | Coverage (\$) | 0.00 |
| Claim No. | S1M03LPY | Excess (\$) | 0.00 |
| Assign From | OH VALE | Assign Date | 09/11/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | HYUNDAI ELANTRA (A) | c.c | 1591 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | KMHD841CMHU309014 | Colour | METALLIC BLUE |
| Odometer | 102314 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 205/55 R16 | YOKOHAMA | 9 mm |
| L/H Front Tyre | 205/55 R16 | YOKOHAMA | 9 mm |
| R/H Rear Tyre | 205/55 R16 | YOKOHAMA | 9 mm |
| L/H Rear Tyre | 205/55 R16 | YOKOHAMA | 9 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 06/11/2021 | Inspection Date | 10/11/2021 |
| Survey held at | EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |