## Veron Chen (LKKAuto)

From: Simon Ho (LKKAuto)

Sent: Tuesday, 16 November 2021 10:46 AM

To: Veron Chen (LKKAuto)

Subject: RE: SKW 1959 PAPER SURVEY-CS3/CTI21006098/T1vc-1

Dear Veron,

Audit check done for SKW1959B without problem.

Best Regards,

**Simon Ho** 

LKK Auto Consultants Pte Ltd

Phone: 6256-3561| email: <u>simonho@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





Save the Earth Print only when necessary

From: Veron Chen (LKKAuto)

Sent: Tuesday, 16 November, 2021 8:00 AM

**To:** Simon Ho (LKKAuto)

Subject: FW: SKW 1959 PAPER SURVEY-CS3/CTI21006098/T1vc-1

Dear Simon

File for re-audit.

Best Regards,

Veron Chen | Case Handler

**LKK Auto Consultants Pte Ltd** 

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taufikh (LKKAuto)

Sent: Monday, 15 November 2021 9:31 PM

To: Veron Chen (LKKAuto) < <a href="mailto:veronchen@lkkauto.com">veronchen@lkkauto.com</a>>

Subject: SKW 1959 PAPER SURVEY

Hi Veron,

Attached revised paper survey. Below the 2 items check and verified.

Item tailgate multiplex computer same as tailgate auto damper as attached found in views system, photo attached item cracked taken in resurvey.

Item Rear fender LH , lower portion crushed , is the rear fender LH of car, lower part of fender is bent buckled. Price revised to \$1245.

Regards Taufikh