



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN			Ref: CC4/ASM21011484/Ups3q2 Date: 15/02/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKQ 2265U	Veh. Inspected	GBJ 7256G
	Policy No.	GA532892	Coverage (\$)	0.00
	Claim No.	S1M03LGK	Excess (\$)	0.00
	Assign From		Assign Date	10/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA REGIUS ACE DX (A)	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GDH2011024196	Colour	WHITE
	Odometer	68955 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	MICHELIN	6 mm
	L/H Front Tyre	195 R15	MICHELIN	6 mm
	R/H Rear Tyre	195 R15	MICHELIN	6 mm
	L/H Rear Tyre	195 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/11/2021	Inspection Date	10/11/2021
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	