Hui Zhen (LKK Auto)

From: Hui Zhen (LKK Auto)

Sent: Monday, 15 November 2021 5:17 PM

To: 'Jessie'; SUR

Subject: GBE 7405U / OD / DOA: 3/11/2021

Dear Jessie,

As instructed by our client, please proceed to repair the insured vehicle GBE 7405U at repair cost not more than \$8,000.00 on Lump Sum basis (Excess \$0).

If there are any check items or supplementary items, please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserves their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: $\underline{\text{huizhen@lkkauto.com}}$ | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)