

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 11 Nov 2021

## **Preliminary Advice**

Insured : SMV2012H

Vehicle No

TP Vehicle : SHC107R  
No

Accident Date : 08/11/2021

Make : TOYOTA PRIUS

Assignment Date : 10/11/2021

Date of : 10/11/2021

Est. Duration of : 5  
Repair

Inspection At : DING AUTOMOTIVE PTE LTD (HQ)  
31 CORPORATION ROAD  
SINGAPORE 649825

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 14,773.58

Revised Amount :S\$ 6,699.80

Check Items (Estimated) :S\$ 337.38

Total :S\$ 7,037.18

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

|                   |      |
|-------------------|------|
| Salvage Value     | :S\$ |
| Margin for Repair | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.