

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 15 Nov 2021

Preliminary Advice

Insured Vehicle No : GBH2666A
TP Vehicle No : SMQ5629K
Make : HYUNDAI AD AVANTE
Date of Inspection : 11/11/21
Inspection At : ZOOM AUTOWERKS PTE LTD

Accident Date : 10/11/2021
Assignment Date : 11/11/2021
Est. Duration of Repair : 4

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,857.36
Revised Amount	:S\$	5,133.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,133.44
Lump Sum Repair	:S\$	4,100.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	36,910.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,090.00

Remarks

- (X) The vehicle is economical for repair
() The vehicle is not economical for repair
() Part-by-Part repair
(X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.