



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM21011516/Kpa3q2 Date: 12/12/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 2695X	Veh. Inspected	SFY 300G	
Policy No.	P2426680	Coverage (\$)	0.00	
Claim No.	S1M03LW9	Excess (\$)	0.00	
Assign From		Assign Date	11/11/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ A20 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD1760432J068073	Colour	METALLIC SILVER	
Odometer	100133 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45Z R17	HABILEAD	3 mm	
L/H Front Tyre	225/45Z R17	HABILEAD	3 mm	
R/H Rear Tyre	225/45Z R17	HABILEAD	4 mm	
L/H Rear Tyre	225/45Z R17	HABILEAD	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S & FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/11/2021	Inspection Date	11/11/2021	
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	