

08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT121011518/4v43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMPCSNW00176032100

Claims No. SNM21D206468/C02/TANCHC

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour:

A/C:

Sp. Reading

T/Radio:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



29/11/14 4/5 @ 14,000 confirmed with Elin (Red 24,764.62, 63%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/11/21-typist

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$ SI

) Photos

) Others

TOTAL

Report Format: Merimen

Lump Sum / L.B. (\$ 14,000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	247F
Vehicle Details	
Vehicle No.:	SNA5110L
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2021
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	07157498N52B25AF
Chassis No.:	WBAFP32030C545335
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$45,866.00
Original Registration Date:	16 Aug 2010
First Registration Date:	16 Aug 2010
Transfer Count:	3
Actual ARF Paid:	\$45,866.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Aug 2030
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,914.00
COE Rebate Amount:	\$28,835.00
Total Rebate Amount:	\$28,835.00

The information contained herein is correct as at 11 Nov 2021

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes C180 Only 2 Years Old At Offers Above \$145k.



Very Low Mileage - 3,698Km
And Well Looked After.
Direct Owner StarAd

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

36 vehicles



bmw 523 2030

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection		bmw 523 2030	Any	Any	> 10 year(s) old	Any	Any	Any	Available
		BMW 5 Series 523i (COE till 05/2030)	\$74,800	\$8,780 /yr	20-May-2010	2,497 cc	152,800 km	Luxury	Available
Full Loan And Flexible Loan Plan Available, High Trade In Welcome, Acceleration Smooth And Quiet, Repairs Up To Date Done, Faster Cal...									
Posted: 11-Nov-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
		BMW 5 Series 523i Sunroof (COE till 09/2030)	\$81,800	\$9,200 /yr	21-Jan-2011	2,497 cc	-	Luxury	Available
Full Loan At Only Monthly \$1,300 Plus, We Provide Lowest Interest Rate Bank Or In-House Full Loan, High Trade In, Ex-Bankruptcy, Bad...									
Posted: 10-Nov-2021 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i									
		BMW 5 Series 523i (COE till 12/2030)	\$83,800	\$9,190 /yr	22-Dec-2010	2,497 cc	-	Luxury	Available
United Motoring Pte Ltd									
Posted: 10-Nov-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
		BMW 5 Series 523i (COE till 08/2030)	\$79,800	\$9,120 /yr	11-Aug-2010	2,497 cc	108,000 km	Luxury	Available
Full Loan Available! Buy With Confidence! In House Loan Or Bank Loan Available! Fast And Easy Loan Approval! Immaculate Condition,...									
Posted: 10-Nov-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
PREMIUM AD									
	Lenovo Multimedia Set & Free Car Vacuum Deal								
Upgrade to Lenovo Smart Android 6+128GB@4G Multimedia player for seamless navigation and entertainment in your car									
Find out more!									
		BMW 5 Series 523i (COE till 05/2030)	\$79,800	\$9,330 /yr	01-Jun-2010	2,497 cc	162,000 km	Luxury	Available
In House Available. Min \$0 Downpayment. Interested Call For Appointment. Consignment Unit									
Posted: 08-Nov-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
PREMIUM AD									
		BMW 5 Series 523i (COE till 11/2030)	\$87,800	\$9,690 /yr	01-Dec-2010	2,497 cc	140,000 km	Luxury	Available
Pristine Condition! Brand New Full Set M5 Body-Kit! All Wear And Tear Parts Done Up! 100% Loan Available From 1.88% P/A! 2 Years Wa...									
Platinum Motoring									
Posted: 08-Nov-2021 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i									
PREMIUM AD									
		BMW 5 Series 523i Sunroof (COE till 07/2030)	\$100,000	\$11,470 /yr	30-Jul-2010	2,497 cc	174,000 km	Luxury	Available
M-Sport Front And Back Bumper, Front Lip, Remus Dual Exhaust With Cert. Front Dotted Brembo Rotor Size 402mm. Back Dotted Bremb...									
360 VR Cars									
Compare									

Compare

Submit to insurance



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

11 November 2021

REG NO.: SNA 5110 L
MAKE/MODEL: BMW 523i

NOT Approved
11/11/21
2/5 \$14,000 10 days
take place later

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
2	Front headlamps o/s era n/s n1 3142.25	\$ 6,284.50 1pc
2	Front grilles scR	\$ 291.40
1	Front bumper m/merged 1357.90	\$ 1,653.55
2	Front bumper fog lamps n1	\$ 942.80 X
1	Front bumper inner sponge n1	\$ 165.00
1	Front bumper centre lower grille n1	\$ 68.00 X
2	Front bumper side grilles n1	\$ 166.30 X
2	Front bumper side grille mouldings n1	\$ 152.50 X
1	Front bumper logo n1	\$ 59.00
1	Front bumper reinforcement n1	\$ 726.00 X
2	Front bumper side retainers n1	\$ 72.40 X
1	Front bumper top rubber seal n1	\$ 90.00 X
2	Front bumper nozzle motor assy n1	\$ 390.00 X
4	Front bumper PDC sensors n1	\$ 1,527.60 X
1	Rear windscreen moulding n1	\$ 95.40 X
1	Rear boot lid n1	\$ 1,658.00
2	Rear boot hinges n1	\$ 450.00 X
1	Rear boot inner trim n1	\$ 235.00 X
2	Rear boot lamps scR/cne	\$ 780.00
1	Rear boot lock n1	\$ 348.24 465.00
1	Rear boot logo n1	\$ 60 79.00
1	Rear boot rubber n1	\$ 225.00
2	Rear taillamps cne 605 x 2 =	\$ 1210.00 1,310.00
1	Rear end panel 3065.00	\$ 920.11 1,018.50
1	Rear end panel inner garnish n1	\$ 266.00 289.00
1	Rear keyless sensor n1	\$ 245.00 X
1	Rear bumper n1	\$ 1530 1,790.00
1	Rear bumper inner pad n1	\$ 182 268.00
1	Rear bumper inner frame garnish n1	\$ 195 335.00
1	Rear bumper lower diffuser n1	\$ 405 485.00
1	Rear bumper lower tray cne	\$ 168.00
2	Rear bumper reflectors n1	\$ 230.00 X
1	Rear bumper reinforcement n1	\$ 615 685.00
1	Rear bumper lower tray o/s cne	\$ 188 340.00
2	Rear bumper side holders n/s n1 o/s n1	\$ 135 278.60 1pc
4	Rear bumper PDC sensors Shuka 180 x 2 = 360	\$ 1,436.00 2pc
		\$ 25,454.55

	c/f:	\$	25,454.55
1	Rear bumper tow hook cover <i>de</i>	\$	45.00 ✓
1	Control unit for rear function module <i>shokd</i>	\$	365.00 ✓
1	Rear floor board <i>an</i>	\$	485.00 X
1	Rear floor panel <i>R</i>	\$	1,495.00 X
1	Rear exhaust silencer <i>R</i>	\$	1,980.00 X
2	Rear exhaust mountings <i>an</i>	\$	90.00 X
2	Rear exhaust chrome tail pipes <i>an</i>	\$	270.00 ✓
2	Rear fenders <i>an</i>	\$	3,100.00 X
2	Rear fender inner trims <i>an</i>	\$	794.00 X
		\$	34,078.55
	Less 5%	\$	1,703.93
		\$	32,374.62

SPECIAL NETT ITEMS

1	Front bumper clip (1 set) <i>nee</i>	\$	60.00 <i>50</i>
1	Front number plate with holder <i>seef</i>	\$	60.00 <i>40</i>
1	Rear winddcreen sealant <i>an</i>	\$	80.00 X
1	Rear bumper clip (1 set) <i>nee</i>	\$	60.00 <i>50</i>
1	Rear number plate with holder <i>DO</i>	\$	60.00 <i>40</i>
		\$	320.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 <i>330</i>
3	To remove and refit front sensor.	\$	11 150.00 X
4	To remove and refit rear reverse sensor.	\$	150.00 <i>50</i>
5	To transfer boot lid mechanism and wiring assembly.	\$	150.00 <i>60</i>
6	To remove and refit rear windscreen glass.	\$	11 180.00 X
7	To remove, refit and replace exhaust silencer and mountings.	\$	180.00 <i>80</i>
8	To apply undercoating.	\$	200.00 <i>80</i>
9	Panel beating.	\$	2,500.00 <i>1400</i>
10	To re-spray painting on the affected areas.	\$	2,400.00 <i>1500</i>
		\$	6,070.00

GRAND TOTAL :

\$ 38,764.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1493787
5%
P-14190.97
S.N-180.00
L-3200