

Our Ref: YQ1224D211109

Date: 13/12/2021

Your Ref:

AIIG Asia Pacific Insurance Pte Ltd  
No. 78 Shenton Way #07-16  
AIIG Building  
Singapore 079120  
**Attn: Motor Claims Department**

Dear Sir / Madam

**Traffic Accident Along** MacPherson Road

**Involving** YQ1224D **and** GBB1458Y **On** 09/11/2021

We/I, Goldbell Leasing Pte Ltd (NRIC / ROC No: 199001196N), the registered owners of m/vehicle - YQ1224D at all material times of the above accident. Our/my vehicle was surveyed by " AIIG Asia " authorized appraiser and we / I based our / my claims on his recommendation for S\$ 7,250-00 being the repair for 05 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle GBB1458Y when the same was involved in the aforesaid accident with our/my m/vehicle - YQ1224D.

We/I whereby you are the insurers of m/vehicle GBB1458Y and the driver/owner was caused solely by the negligence of your insured and as a result thereof of our / my m/vehicle - YQ1224D has suffered loss and damage as follows:

Cost of repairs	S\$	<u>7,250-00</u>
LOU for pre-repair notice 02 days @ S\$ <u>80-00</u> [2998 cc]		<u>160-00</u>
LOU Fee for <u>05</u> days @ S\$ <u>80-00</u> [2998 cc]		<u>400-00</u>
Rental Fee Invoice No: _____		_____
GIA / LTA search fee		<u>7-45</u>
Towing Fee (Cash Sale No _____)		_____
Survey Fee		_____
<b>Total Amount</b>	<b>S\$</b>	<u>7,817-45</u>

We/I enclose herewith copies of the supporting documents for vehicle no. YQ1224D as follows:-


- (i) Motor Accident Report & Documents;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our/my claims as soon as possible.

Please remit us/me your settlement sum in favor of M/s Liu's Brother Auto Engineering Workshop. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,

  
f \_\_\_\_\_

The owner of m/vehicle YQ1224D  
Messers Goldbell Leasing Pte Ltd  
cc. Liu's Bro Auto Engineering Workshop

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbro@gmail.com

Invoice/Ref No: YQ1224D211109

**Final Bill**

<b>Customer</b>		<b>Date:</b>	13-12-21
<b>Name:</b>	AIG Asia Pacific Insurance Pte Ltd	<b>Vehicle No:</b>	YQ1224D
<b>Address:</b>	Motor Claims Department	<b>Model/Make:</b>	Mitsubishi
	78 Shenton Way #07-16		Canter FEB21ER4SDEN (CBU)
	AIG Building		
	Singapore 079120		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 1,133.40	\$ -
2	Bumper Clips 1 set	\$ 50.00	SN \$ -
3	Grille	\$ 1,105.70	\$ -
4	Grille Clips 1 set	\$ 30.00	SN \$ -
5	Grille "Mitsubishi Logo" Grille	\$ 187.00	N \$ -
6	"Canter" Emblem	\$ 86.00	\$ -
7	DashBoard (Fuel Box) Cover	\$ 579.00	\$ -
8	Front Lh Bumper Side	\$ 375.00	\$ -
9	Bumper Side Clips 01 set	\$ 45.00	SN \$ -
10	Door	\$ 2,001.50	\$ -
11	Door Hinges 02 pcs @ S\$115.00)	\$ 230.00	\$ -
12	Door Glass Outer Moulding	\$ 171.00	\$ -
13	Door Draught Weatherstrip	\$ 408.40	\$ -
14	Door Inner Trim Boards	\$ 593.90	\$ -
15	Door Inner Trim Boards 1 set	\$ 45.00	SN \$ -
16	Door Lock	\$ 367.20	\$ -
17	Step Panel Garnish	\$ 647.40	\$ -
18	Step Garnish Inner	\$ 613.20	\$ -
19	Corner Panel	\$ 474.60	\$ -
20	Side Mirror Arm	\$ 513.80	\$ -
21	Side Mirror "Square"	\$ 107.70	\$ -
22	Side Mirror "Round"	\$ 110.50	\$ -
23	Head Lamp	\$ 1,712.80	\$ -
24	Head Lamp Clips 01 set	\$ 30.00	SN \$ -
25	Head Lamp Garnish	\$ 365.10	\$ -
26	Signal Lamp	\$ 324.30	\$ -
27	Signal Lamp Clips 01 set	\$ 20.00	SN \$ -
28	Wiper Tank	\$ 222.50	\$ -
	To check all wiring & electrical component for proper function	\$ 80.00	\$ -
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	\$ -
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,000.00	\$ -
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc ...	\$ 450.00	\$ -
	Remove & reinstall Glass to facilitate repairs & perform water test	\$ 120.00	\$ -
	To apply Rust Proofing , resal tuffcoating treatment on accident area	\$ 80.00	\$ -

**Total Parts & Labour of estimate for damaged vehicle****\$ 15,560.00****Total amount in Lump Sum Basis for repaired vehicle****\$7,250.00**

SDLS: Seven Thousand Two Hundred Fifty Only



M/s Liu's Bro Auto Engrg Wks

Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 11 Nov 2021 / 16:22:36

Receipt Date/Time : 11 Nov 2021 / 16:22:23

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-211111-002592

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBB1458Y As at 09 Nov 2021/09:15:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - GBB1458Y Enquiry Fee 20211111162045942927	7.00	0.49	7.49
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
	<b>Paid By</b>			
	426588XXXXX1485	eNETS Credit Card		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.