

⏪

⏩

1 of 2 ?

⏴


⏵

100% ▾

📄 ✓

🖨

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref: CS3/LPC21011548/Vvf3	
300 BEACH ROAD			Date: 12/11/2021	
#17-04/07 THE CONCOURSESINGAPORE 199555			Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLK 4844E	Veh. Inspected	SMD 8219J	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/21/21/VP05/025140	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	12/11/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/11/2021	Inspection Date	12/11/2021	
Survey held at	8, Kaki Bukit Avenue 4 @ Premier, #04-20			
Repairer	A-TEC AUTOMOTIVE PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				