From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Singapore 408933

Paya Ubi Industrial Park

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

Singapore 079120

#09-16

Date: 12 Nov 2021 Attn:

Preliminary Advice

Vehicle No : SDQ3339S Accident Date : 08/11/2021 Make : AUDI Q3 SPORTBACK Policy No. : 7210054279 : 12/11/2021 Excess Assignment Date : S\$0.00 Est. Duration of Repair Date of Inspection : 10/11/21 : 8

Inspection At : PREMIUM AUTOMOBILES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,078.00
Revised Amount	:S\$	24,413.00
Check Items (Estimated)	:S\$	3,299.00
Total	:S\$	27,712.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$

Pre-Accident Value :S\$ 175,000.00 COE / PARF Rebate :S\$ 82,484.00

Salvage Value :S\$

Margin for Repair :S\$ 92,516.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly	
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .