Elaine (LKK Auto)

To: Choo, Thelma

Cc: Claims - Motor Survey; SUR; Huey Yon (LKKAuto); Veron Chen (LKKAuto)

Subject: RE: Survey Report & Invoice of Vehicle PC 3459K Ref: CMTD2103355/THE

Attachments: LKKAdjustment-1.pdf; LKKInspection-1.pdf

Dear Thelma,

Enclose final report of PC 3459K.

Thank you.

Best Regards,

ELAINE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 14 March 2022 4:59 PM **To:** Choo, Thelma; Reports (LKKAuto)

Cc: SUR; Huey Yon (LKKAuto)

Subject: FW: Survey Report & Invoice of Vehicle PC 3459K Ref: CMTD2103355/THE

Importance: High

Dear Thelma,

Refer to the attach is preliminary report.

We will submit our final report shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Choo, Thelma < thelma.choo@sompo.com.sg >

Sent: Monday, 14 March 2022 4:38 PM

To: Reports (LKKAuto) < report@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Huey Yon (LKKAuto) <hueyyon@lkkauto.com>

Subject: RE: Survey Report & Invoice of Vehicle PC 3459K Ref: CMTD2103355/THE

Importance: High

Dear Elaine,

We refer to the attached Survey Report

We note that the finalized Cost of Repair submitted by the Third Party Workshop does not tally with the surveyor recommendation

1)	Repair Cost inc 7%		S\$	13,375.00
2)	Loss of Use @\$150 days	X 12	SS	1,800.00
3)	LTA search @ 50% liability		S\$	7.45



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$2,000.00 NETT)	
--	--

Report Ref No. CS/SMO21011559/Kvf3e2

Please assist to verified with the surveyor on an urgent basis

Thank you

Best Regards
Thelma Choo
Claims Executive

D: 6322 4681 | **T**: 6461 6555



Innovation for Wellbeing

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Elaine (LKK Auto) < report@lkkauto.com>
Sent: Wednesday, January 19, 2022 4:48 PM
To: Choo, Thelma < thelma.choo@sompo.com.sg>

Cc: Claims - Motor Survey < MotorSurvey@sompo.com.sg >; 'SUR' < sur@lkkauto.com >; 'Huey Yon

(LKKAuto)' <hueyyon@lkkauto.com>

Subject: Survey Report & Invoice of Vehicle PC 3459K Ref: CMTD2103355/THE

EXTERNAL SENDER: Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Thelma,

Enclose Survey Report of PC 3459K.

Thank you.

Best Regards,

ELAINE | Reports LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)