

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/014/2021
DATE : 15-NOV-2021

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
S(189556)
TEL : 65947060/67886616
FAX :
MOTOR CLAIMS

OWNER'S NAME : LOCK YIN PI
ADDRESS : 15 FABER PARK

S(129105)
TELEPHONE NO : 8126 6089

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1
VEHICLE NO : SLU2556Y
MODEL CODE : GT38KGC
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT
ENGINE NO : FB16YB77134
CHASSIS NO : JF1GT3KC5JG024326
MILEAGE : 1 KM
DATE IN : 15/11/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 15/11/2021

Print Date : 27/12/2021
Print Time : 14:47:04

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU2556Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	REVERSE2	TO SUPPLY AND INSTALL 2-POINT REVERSE SENSOR	300.00	180.00
2	ZZ/001	TO REPLACE REAR BUMPER,BUMPER BEAM,TAILGATE	1740.00	1120.00
3	ZZ/002	TO RESPRAY REAR BUMPER,BUMPER BEAM,TAILGATE	1470.00	840.00
4	ZZ/003	TRANSFER TAILGATE INNER TRIMS & MECHANISM	150.00	150.00
5	ZZ/004	REMOVE & REPLACE REAR WINDSCREEN	300.00	300.00
6	ZZ/005	TO INSTALL REAR WINDSCREEN SOLAR FILM	145.00	145.00
7	ZZ/006	FAULT DIAGNOSTIC (RESET)	280.00	.00
8	ZZ/007	TO CONDUCT REAR LIGHTING TEST	150.00	150.00
9	ZZ/008	TO CONDUCT REAR PROTECTANT COATING	500.00	.00
10	ZZ/009	TO CONDUCT REAR ANTI RUST COATING	580.00	.00
11	ZZ/10	SUNDRIES	100.00	20.00
TOTAL LABOUR CHARGES			5715.00	2905.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU2556Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
1	BUMPER FACE R XV	57704FL250	601.50				OK
2	BRKT SD R XV RH	57707FL400	12.10				X
3	BRKT SD R XV LH	57707FL410	12.10				X
4	BRKT CORNER R SD RH	57707FL460	21.60				X
5	BRKT LWR R	57707FL510	100.80				X
6	BEAM COMPL R EU	57711FL0419P	203.00				OK
7	PANEL COMPL R GAT	60809FL0009P	940.00				OK
8	GLASS ASSY R G	63019FL030	1062.00				OK
9	DAM RUBBER	65245FL000	18.00				OK
10	LENS & BODY COMPLRH	84912FL041	378.00				X
11	CLIP 2 PCS	909140062	5.76				OK
12	GARNISH SX	91111FL010NN	216.00				X
13	ORNAMENT ASSY F SIX	91174SA181	68.40				X
14	PROTECTOR UP FHI	91713FL000	7.20				X
15	PROTECTOR SD RH FHI	91713FL010	3.60				X
16	PROTECTOR SD LH FHI	91713FL020	3.60				X
17	PROTECTOR LWR B FHI	91713FL040	5.40				X
18	LETTER MK R	93079FL100	90.00				OK
19	LETTER MK R XV	93079FL140	36.00				OK
SUB TOTAL			2956.26	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			591.25	0.00	0.00	0.00	
GRAND TOTAL			2365.01	0.00	0.00	0.00	
OVERALL TOTAL			2365.01				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLU2556Y

NETT ITEM	2956.26
LESS 20 %	-591.25
NETT AMOUNT	2365.01
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	2905.00
TOTAL SPARE PARTS CHARGES	2365.01
TOTAL CHARGES	5270.01
ADD 7 % GST	368.90
GRAND TOTAL	5638.91