



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21011618/Buf3e2	
			Date: 15/12/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 2610G		Veh. Inspected	SMY 51S
Policy No.			Coverage (\$)	0.00
Claim No.	21/21/21/VC00/025116		Excess (\$)	0.00
Assign From	ONG LI LI		Assign Date	15/11/2021
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180 AVG		c.c	1595
Engine No.	HIDDEN		Year of Reg.	2019
Chassis No.	WDD2050402R513421		Colour	BLUE
Odometer	38066 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		225/50 R17	DUNLOP	5 mm
L/H Front Tyre		225/50 R17	DUNLOP	5 mm
R/H Rear Tyre		225/50 R17	DUNLOP	5 mm
L/H Rear Tyre		225/50 R17	DUNLOP	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2021		Inspection Date	17/11/2021
Survey held at	T & S MOTOR SERVICE BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 . SINGAPORE 569538			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	