



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|-------------------------|-----------------|--------------------------------|--|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 | | | Ref: CS3/LPC18019875/R1tf3e2-1 | |
| | | | Date: 29/11/2021 | |
| | | | Code: LPC2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | YK 3778R | Veh. Inspected | GBH 7054H | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | 18/18/18/VC05/021087 | Excess (\$) | 0.00 | |
| Assign From | GERALD POH | Assign Date | 15/11/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | CITROEN BERLINGO L2 1.6 | c.c | 1560 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | VF77FBHYMHJ766221 | Colour | GREY | |
| Odometer | 12402 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | KLEBER | 6 mm | |
| L/H Front Tyre | 195/65 R15 | KLEBER | 6 mm | |
| R/H Rear Tyre | 195/65 R15 | KLEBER | 6 mm | |
| L/H Rear Tyre | 195/65 R15 | KLEBER | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND N/S REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 30/10/2018 | Inspection Date | 05/11/2018 | |
| Survey held at | 7A JALAN PAPAN | | | |
| Repairer | THIAM HENG MOTOR | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |