

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC7024A

Make : HYUNDAI

Model : I-40

Date: 15/11/2021

Insurance: AIG

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
1	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER SIDE BRACKET RH			\$35.60
1	REAR BUMPER REFLECTOR LAMP RH			\$32.00
1	EXHASUT SILENCER RH			\$967.70
1	EXHAUST PIPE CENTRE			\$730.10
1	EXHAUST PIPE HANGER			\$117.10
	SUB TOTAL		575	\$2,457.50
	LESS 20%		460	\$491.50
	DISCOUNTED TOTAL			\$1,966.00
1	REAR BUMPER REVERSE SENSOR		185.70	\$135.70
1	REAR BUMPER RUBBER MAT			\$50.00
				\$185.70
	Labour Charge			
	PANEL BEATING			\$450.00
	SPRAY PAINTING CHARGE			\$300.00
	REMOVE/ REFIX EXHAUST PIPE		560	\$150.00
	REMOVE/ REFIX REVERSE SENSOR			\$60.00
	TOTAL LABOUR		1205.70	\$960.00
	ESTIMATE TOTAL		1549.50	\$3,111.70
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payable 17415447

in p' 15/11/2021 5pm

Lb's Resurvey after repair

2 days

Page 1

LKK Auto Consultants