

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Chen Chee Kiong
CLAIM DEPARTMENT
DID : 66547607
FAX : 66547540

Date : 19/11/2021

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057 Accident Date : 11/10/2021

Vehicle No : YP -3066-K Make & Model : ISUZU NQR75UL5A 5.2 DIESEL Y (M) EURO 5

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Special Nett Item			
1	REAR LHS CABIN 1ST PANEL	800.00	? 600
1	REAR LHS CABIN 2ND PANEL	800.00	? 600
1	REAR LHS CABIN 3RD PANEL	800.00	? 600
1	REAR LHS ADVERTISING STICKER	2,000.00	? X
	Sub Total	4400.00	1800
Labour & Misc			
	LABOUR TO REMOVE AND REPLACE REAR LHS CABIN PANEL	1,000.00	? 400 ✓

2200

-20%: 1750

2 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Handwritten:
Luo Qian
52880282
12/11/21
4/S
After repair photo's

PAGE : 1