



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BW WORKSHOP SERVICES PTE. LIMITED

291 KAKI BUKIT AVE 1.
SHUN LI INDUSTRIAL PARK,
SINGAPORE 416080
RAIZE
INN EE

NO: DLI9248702

PAGE: 1

DATE: 15/02/2022

A/C CODE: LDBW001

TERMS: CR

P/O NO: ES82D

Part No	Description	Location	Qty
Our D/O No: DDO9026175			
1 T52159-B1310-E0	RR BUMPER	DDS	1
2 T52156-B1090	REAR BUMPER RETAINER LH	DU1AD50-1 ✓	1
3 T52155-B1090	REAR BUMPER RETAINER RH	DU1AD52-3 ✓	1
4 T52169-B1030	RR BUMPER DIFFUSER	DDS	1
5 T52752-B1050	REAR BUMPER COVER RH	DDS	1
6 T52753-B1050	REAR BUMPER COVER LH	DDS	1
7 T76801-B1070	TAILGATE OUTER GARNISH	DU1V14 ✓	1
8 T81920-B2040	REAR BUMPER REFLECTOR	DU1A12 ✓	1
	LH		
9 T81910-B2040	REAR BUMPER RELECTOR	DU1A1 ✓	1
	RH		
10 T58307-B1070	END PANEL OUTER	DB2J21	1
11 T58308-B1030	END PANEL INNER	DDS	1
12 T64716-B1100-C0	END PANEL TOP GARNISH	DDS	1
13 T67005-B1550-B0	TAILGATE	DDS	1
14 T69350-B2410	TAILGATE LOCK	DU1B186 ✓	1
15 T67881-B1070	TAILGATE WEATHERSTRIP	DDS	1
16 T64781-B1030-B0	TAILGATE INNER	DDS	1
	TRIMBOARD		
17 T61061-B1010	REAR WHEEL ARCH RH	DDS	1
18 T65637-B1121	REAR FENDER SHIELD RH	DDS	1
19 T81270-B5020	LIC PLATE LAMP	DU1A23 ✓	1
20 T58311-B1070	SPARE TYRE PANEL	DDS	1

Print / LSK / 15/02/2022 11:08:00 am

...Cont'd





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BW WORKSHOP SERVICES PTE. LIMITED

NO: DLI9248702

PAGE: 2

Part No	Description	Location	Qty
21	T58351-B1040	SPARE TYRE PANEL CLAMP	DDS 1
22	T58410-B1160-B1	SPARE TYRE TOP BOARD	DDS 1
23	T58582-B1010	REAR FLOOR MAT	DDS 1
24	T62640-B1160-C0	REAR FENDER TRIM LH	DDS 1
25	T62630-B1160-C0	REAR FENDER TRIM RH	DDS 1
26	T62552-B1040-C0	REAR SEAT COVER LH	DDS 1
27	T62551-B1050-C0	REAR SEAT COVER RH	DDS 1
28	T53121-B1120	RAD GRILLE MLDING	DU2A3 ✓ 1
29	T52119-B1410-A0	FR BUMPER	DDS 1
30	T52116-B1061	FR BUMPER RETAINER LH	DU1AD44-1 ✓ 1
31	T52115-B1060	FR BUMPER RETAINER RH	DDS 1
32	T53101-B1130	FR BUMPER GRILLE	DDS 1
33	T52129-B1080	FR BUMPER LOWER LIP	DU2H3 ✓ 1
34	T52130-B1010	FR BUMPER CENTER BRACKET	DU1D1-1 ✓ 1
35	T81150-B1431	HEADLAMP ASSY LH	DB2BB5 1
36	T81110-B1431	HEADLAMP ASSY RH	DB2AA1 1
37	T52713-B1160	FR FOG LAMP COVER LH	DDS 1
38	T52712-B1170	FR FOG LAMP COVER RH	DDS 1
39	T16400-B1480	RADIATOR	DB1A14 1
40	T16711-B1100	FAN SHROUD	DBCC1S 1
41	T17700-B1140	AIR CLEANER ASSY	DB1D5 1
42	T17940-B1030	INTERCOOLER	DU1AC32 ✓ 1
43	T88460-B1030	CONDENSER	DB2H 1
44	T88712-B1260	HOSE SUCTION	DDS 1
45	T88716-B1330	LIQUID PIPE	DD1F19 1
46	T86510-B1120	HORN	DDS 1
47	T53301-B1150	FR BONNET	DB1C33 1
48	T53401-B1070	FR BONNET HINGE RH	DU1AD33-4 ✓ 1

Print / LSK / 15/02/2022 11:08:01 am

...Cont'd





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BW WORKSHOP SERVICES PTE. LIMITED

NO: DLI9248702

PAGE: 3

Part No	Description	Location	Qty
49	T53402-B1070	FR BONNET HINGE LH	DU1AD33-5 ✓ 1
50	T53510-B1130	FR BONNET LOCK	DU1B67 ✓ 1
51	T53341-B1090	FR BONNET INSULATOR	DB2DD6 1
52	T84340-B2060	BRAKE SWITCH	DDS 1
53	T53812-B1320	FR FENDER LH	DB1B14 1
54	T53811-B1320	FR FENDER RH	DB1B5 1
55	T75602-B1010	FR WHEEL ARCH LH	DU2D6 ✓ 1
56	T85381-B1100	FR WIPER NOZZLE RH	DDS 1
57	T53208-B1030	TOP BEAM	DDS 1
58	T53216-B1100	SUPPORT PANEL TOP	DDS 1
59	T53202-B1090	SUPPORT PANEL VERTICAL RH	DDS 1
50	T53203-B1050	SUPPORT PANEL VERTICAL LH	DDS 1
51	T53215-B1100	HOOD LOCK SUPP	DDS 1
52	T53218-B1080	SUPPORT PANEL LOWER	DDS 1
53	T53706-B1010	BRACE PANEL LH	DDS 1
54	T53705-B1010	BRACE PANEL RH	DDS 1
55	T53209-B1020	FRONT CENTER BRACE PANEL	DB1G6L 1
56	T53395-B1010	FRONT SIDE GUIDE RH	DU1G1-1 ✓ 1
57	T53396-B1010	FRONT SIDE GUIDE LH	DU1G1-1 ✓ 1
58	T52141-B1040	FR CHASSIS BRACKET RH	DDS 1
59	T90044-68378	COWLING CLIP	DDS 10
70	T17882-B1030	AIR HOSE	DDS 1
71	T53152-B1040	CONDENSER TOP GUIDE NO.1	DDS 1
72	T53039-B1010	CONDENSER TOP GUIDE NO.2	DDS 1
73	T53037-B1010	CONDENSER PLATE RH	DDS 1

Print / LSK / 15/02/2022 11:08:02 am

...Cont'd





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: BW WORKSHOP SERVICES PTE. LIMITED

NO: DLI9248702

PAGE: 4

Part No	Description	Location	Qty
74 T53038-B1010	CONDENSER PLATE LH	DDS	1
75 T61032-B1070	TAILLAMP PANEL LH	DDS	1
76 T61031-B1070	TAILLAMP PANEL RH	DDS	1
77 T62930-B1020	QTR VENT LH RH	DUIAC5	2
78 T90189-06065	CLIP (90041-89021)	DD1A152	10
79 T57117-B1040	FRONT CHASSIS SIDE PLATE RH	DDS	1
80 T51095-B1010	SPARE TYRE PANEL HOOK	DDS	1

TOTAL QUANTITY: 99

SEND: KAKI BUKIT AUTOBAY #02-20 (MR HENG)

Print / LSK / 15/02/2022 11:08:02 am

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

Mr 15/2/22

E. & O. E.

GOODS RECEIVED BY

