

Our Job Ref No : 305494448
Date : 25/11/21

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHC3105B

Date of Accident : 14.11.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBH 771S

2. The finalized amount shall be:

(a) Spare Parts after List discount \$56.50

(b) Labour Charges \$880.00

Total for Part-By-Part Repair Cost \$936.50

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Signature : 

Name : LIM T S

Name : TAUFIKH

Tel : 62148398

Date : 07/12/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	---		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305494448
REGN NO : SHC3105B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 31.05.2019
DATE/TIME IN : 14.11.2021 09:50
ACCIDENT DATE : 14.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50
0002 28-01-0302-2017-A	RR FENDER (PETROL ONLY) LH	1	40.00	250	40.00

SUB-TOTAL : 56.50

JOB NATURE

0000 PB	PANEL BEATING-SHC3105B	350.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 L	R/I REVERSE SENSORS	30.00

SUB-TOTAL : 880.00

TOTAL : 936.50


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO