# Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Tan Siok Thiew Jas 18 Nov 2021 Date:

## **Preliminary Advice**

Insured Vehicle No : GBJ7799G

TP Vehicle No : SHA8271G Accident Date : 15/11/2021 Make : TOYOTA PRIUS HYBRID Assignment Date : 16/11/2021

Date of Inspection : 16/11/2021 Est. Duration of Repair : 5

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

> **59 LOYANG DRIVE** SINGAPORE 508969

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,439.20
Revised Amount	:S\$	2,993.00
Check Items (Estimated)	:S\$	2,028.20
Total	:S\$	5,021.20

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	dly
	let us have your authorisation.	

(		The vehicle is uneconomical	≀to l	be repaired	. vou are advise	ď	to invite	e tend	ler f	or t	he wrec	:k
١	. ,			bo ropanoa	, you alo aavioo	ч		COLIC		0, ,	110 11100	

Other comments: Please note that the preliminary advice amount (Revised & Check items) stated are subject to ( X ) consistency check, part prices and labour cost.