

Asher

TOTAL

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautoprote@gmail.com

Asher
HIG / DAD

SJE :

Vehicle Nos : **SJN 5810 D**

Date of Survey :

Model : Toyota Vios

Date of ReSurvey:

Year : 2011

Contacts :

Chassis No : MR053HY9305246190

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 568.30	\$ 568.30 ✓
2	Bootlid logo	1	\$ 68.40	\$ 59.50 68.40
3	Bootlid emblem "VIOS"	1	\$ 65.20	\$ 59.30 65.20
4	Bootlid emblem "E"	1	\$ 58.90	\$ 58.90 ✓
5	Bootlid inner lock	1	\$ 148.60	\$ 105.60 148.60
6	Bootlid weatherstrip	1	\$ 389.50	\$ 175.10 389.50
7	Rear bumper	1	\$ 547.60	\$ 490.00 547.60
8	Rear bumper reflector	2	\$ 63.40 259.30	\$ 126.80 518.60
9	Rear bumper side retainer front	2	\$ 35.20 153.80	\$ 70.40 307.60
10	Rear bumper side retainer rear	2	\$ 92.40 189.20	\$ 184.40 378.40
11	Rear fender inner trim board	2	\$ 489.60	\$ 979.20
12	Rear end panel	1	\$ 588.30	\$ 588.30 ✓
13	Rear end panel top garnish	1	\$ 198.50	\$ 198.50 ✓
14	Rear spare tyre panel	1	\$ 668.70	\$ 668.70
15	Rear spare tyre top board	1	\$ 285.20	\$ 285.20
16	Taillamp	2	\$ 342.00 652.80	\$ 684.00 1,305.60
			Parts Sub Total :	\$ 3369.10 7,076.60
25%			Discount :	\$ 842.28 1,769.15
			PARTS TOTAL :	\$ 2526.83 5,307.45

2011

BTU ✓

NECV ✓

JM ✓

TN ✓

BRV ✓

BRV ✓

NECV ✓

NECV ✓

NDX NN

DDV ✓

BRV ✓

NDX NN

BRV ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00 80.00
2	Bootlid sealant	1	\$ 100.00	\$ 100.00 40.00
3	Rear bumper clips	1	\$ 50.00	\$ 50.00 30.00
4	Rear fender inner trim board clips	2	\$ 50.00	\$ 100.00 100.00
5	Rear end panel sealant	1	\$ 100.00	\$ 100.00 40.00
6	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00 30.00
7	Taillamp seal	2	\$ 60.00 30.00	\$ 120.00 60.00
8	Taillamp clips	2	\$ 50.00	\$ 100.00 30.00
9	Rear bumper reverser sensor	2	\$ 250.00	\$ 500.00 200.00
SPECIAL NETT TOTAL :				\$ 1,200.00 430.00

NNX
NECV
NECV
NNX
NECV
NECV
NECV
NECV
SCV

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 150.00 80.00
2	R&R rear bumper reverse sensor	\$ 100.00 60.00
3	Check wiring	\$ 100.00 100.00
4	Upholstery	\$ 300.00 300.00
5	Panel beating	\$ 1,400.00 600.00
6	Rust proofing	\$ 200.00 200.00
7	Spray painting	\$ 1,400.00 600.00
LABOUR TOTAL :		\$ 3,650.00 1340.00

NNX
NNX
/

Survey Resurvey
16/11/2021 17/11/2021
Tquin Tquin
Min Min
14 rollers 15 rollers

PARTS TOTAL : \$ 5,307.45
SPECIAL NETT TOTAL : \$ 1,200.00
LABOUR TOTAL : \$ 3,650.00
GRAND TOTAL : \$ 10,157.45

Lump sum repair
Repair days 5

Parts 2,526.83
SN 430.00
Labour 1,340.00
4,296.83
@ 20% 859.37
3,437.46

LS 3,450/2

Tquin Min
28/12/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: