

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 1 June 2023 8:56 AM
To: Alfred Toh
Cc: Admin A; claimsdept@sg.cntaiping.com
Subject: [SEEK MANDATE] - Your ref: SNM21D206612 // LKK ref : CC6/CTI21011698/Apa3q2
[ACCIDENT INVOLVING SJK1702A(CHINA TAIPING) AND SLM5344P(TP) ON 15/11/2021]
Attachments: LETTER TO OI.pdf; LKK SURVEY REPORT & PHOTOS.pdf; TP LOD.pdf

Your ref: **SNM21D206612**
LKK ref : CC6/CTI21011698/Apa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING SJK1702A(CHINA TAIPING) AND SLM5344P(TP) ON 15/11/2021

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer "J-MART MOTOR PTE LTD" at **\$6,685.00(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (With 7% GST)	\$ 9,607.18	\$ 5,885.00 (\$5,500.00 + 7%GST)
2. Loss of Rental (8days x \$120.00)	\$ 960.00	\$ 800.00 (8days x \$100.00)
Total	\$ 10,567.18	<u>\$ 6,685.00</u>

Surveyor recommended 6days for repair + 1PRS + 1SUNDAY = 8DAYS.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 30/03/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

