



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21011703/Aqf3n2	
			Date: 10/03/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 877G	Veh. Inspected	SMZ 4746P
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/21/2025	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	17/11/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	AUDI Q2	c.c	999
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WAUZZZGA6KA082553	Colour	GREY
	Odometer	28636 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	12/11/2021	Inspection Date	18/11/2021
	Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	