

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0933/2021/TF
DATE : 17-Nov-21
WIP : 54056

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

YOUR INSURED VEH NO : SHB 877 G

MS First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Hi Adrian

3 days - ok - Johnny Boo

28-Dec-21

OWNER'S NAME : MR ONG BOON LENG
ADDRESS : 97 YISHUN ST 81
#06-04
SINGAPORE 768453
TELEPHONE : HP +65 94873784
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5122544008
VEHICLE NO : **SMZ 4746 P**
MODEL CODE : AUDI Q2 1.0 TFSI S tronic
MODEL YEAR : 28/8/2019
ENGINE NO : CHZC32574
CHASSIS NO : WAUZZZGA6KA082553
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Nov-21
PLACE OF ACCIDENT : ALONG ST THOMAS WALK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 4746 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. <i>(Nec - MS FIRST CAP)</i>	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$ 800.00
4	TO RESPRAY FRONT BUMPER.	\$	1,000.00	\$ 800.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,152.00	\$ 2,152.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 4746 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,042.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 347.00	
3	FRONT BUMPER LOWER CENTER GRILLE	1	\$ 197.00	
4	FRONT BUMPER AIR GRILLE - LH	1	\$ 169.00	
5	FRONT BUMPER AIR GRILLE END CAP - LH	1	\$ 59.00	
6	FRONT BUMPER SPOILER	1	\$ 299.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 156.00	
8	FRONT WHEEL SPOILER - LH	1	\$ 34.00	
9	FRONT BUMPER ADAPTER - LH	1	\$ 36.00	
10	RADIATOR GRILLE	1	\$ 1,411.00	\$ 1,411.00
11	RADIATOR GRILLE STRIKER PLATE	1	\$ 124.00	
12	FRONT BUMPER CARRIER FOAM	1	\$ 78.00	
13	FRONT BUMPER CARRIER	1	\$ 723.00	
14	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 72.00	
15	FRONT BUMPER TOP COVER	1	\$ 100.00	
16	CAUTION STICKER	1	\$ 14.00	
17	A/C STICKER	1	\$ 8.00	
18	HORN - LH	1	\$ 286.00	
19	HORN BRACKET - LH	1	\$ 31.00	
20	FRONT WHEEL HOUSING LINER - LH	1	\$ 196.00	
SUB TOTAL SPARE PARTS			\$ 5,382.00	\$ 1,411.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 4746 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>1,411.00</i>
21	FRONT WHEEL LINER ATTACHMENT PARTS	1	\$ 57.00		
22	HEADLIGHT MOUNTING - LH	1	\$ 118.00		
23	HEADLIGHT - LH	1	\$ 4,915.00		
24	HEADLIGHT LIFT CYLINDER - LH	1	\$ 142.00		
25	HEADLIGHT LIFT CYLINDER HOSE	1	\$ 182.00		
26	RADIATOR AIR GUIDE - LH / UPPER CENTRE / RH	3	\$ 84.00		
27	FRONT WHEEL ARCH TRIM - LH / RH	2	\$ 644.00	<i>\$</i>	<i>643.00</i>
28	FRONT NO. PLATE	S/N	\$ 60.00	<i>\$</i>	<i>60.00</i>
29	SUNDRIES		\$ 300.00		
TOTAL SPARE PARTS		:	\$ 11,884.00	<i>\$</i>	<i>2,114.00</i>
TOTAL LABOUR CHARGES		:	\$ 3,152.00	<i>\$</i>	<i>2,152.00</i>
GRAND TOTAL		:	\$ 15,036.00	<i>\$</i>	<i>4,266.00</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-28/12/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT