

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SNC 3441 J**
 Model : **TOYOTA YARIS CROSS**
 Year : **2021**
 Chassis No : **MXPB102013442**

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Model : TOYOTA YARIS CROSS

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	TAILGATE	1	\$ 1,859.75	\$ ✓ 1,859.75
2	TAILGATE LOGO	1	\$ 78.79	\$ 78.79 60.00
3	TAILGATE EMBLEM 'YARIS CROSS'	1	\$ 70.48	\$ ✓ 70.48
4	TAILGATE OUTER GARNISH	1	\$ 633.50	\$ ✓ 633.50
5	TAILGATE LOCK ASSY	1	\$ 812.77	\$ 812.77 318.00
6	TAILGATE STRIKER	1	\$ 62.24	\$ 62.24
7	TAILGATE INNER TRIM BOARD	1	\$ 499.80	\$ ✓ 499.80
8	TAILGATE WEATHERSTRIP	1	\$ 326.06	\$ ✓ 326.06
9	TAILGATE LAMP	2	\$ 759.13	\$ ✓ 1,518.26
10	TAILGATE WINDSCREEN MOULDING	1	\$ 260.99	\$ ✓ 260.99
11	TAILGATE SMART KEYLESS SENSOR	1	\$ 352.36	\$ 352.36
12	REAR BUMPER	1	\$ 2,208.10	\$ ✓ 2,208.10
13	REAR BUMPER LOWER	1	\$ 786.15	\$ ✓ 786.15
14	REAR BUMPER SIDE RETAINER	2	\$ 162.34 130.00	\$ 324.68 260.00
15	REAR BUMPER BRACKET	2	\$ 114.30	\$ 228.60
16	REAR BUMPER INNER SPONGE	1	\$ 316.52	\$ 316.52
17	REAR BUMPER REINFORCEMENT	1	\$ 621.71	\$ 621.71
18	REAR BUMPER ARCH GARNISH RH	1	\$ 452.40	\$ ✓ 452.40
19	REAR BUMPER REFLECTOR RH	1	\$ 181.25	\$ 181.25 93.00
20	REAR END PANEL	1	\$ 1,043.79	\$ 1,043.79 689.75
21	REAR END PANEL TOP GARNISH	1	\$ 384.27	\$ 384.27 208.00
22	SPARE TYRE PANEL	1	\$ 830.62	\$ 830.62
23	SPARE TYRE PANEL TOP BOARD	1	\$ 302.95	\$ 302.95
24	SPARE TYRE PANEL TOOLS TRAY	1	\$ 480.84	\$ 480.84
25	TAILLAMP RH 1	✓	\$ 858.42	\$ 1,716.84 858.42
26	TAILLAMP LOWER BRACKET RH 1	✓	\$ 124.62	\$ 249.24 124.62
27	REAR FENDER LH	1	\$ 1,196.84	\$ 1,196.84
28	FENDER INNER TRIM BOARD RH 2	✓	\$ 671.20	\$ 1,342.40 671.20
			Parts Sub Total :	\$ 11,898.48 19,142.20
			Discount :	\$ 2,974.62 4,785.55
			PARTS TOTAL :	\$ 8,923.86 14,356.65

25%

DDV
 } NECV
 BRV
 JMV
 NDX
 BRV
 TNV
 BRV
 NECV
 NDX
 BRV
 BRV
 NECV
 NSX
 NSX
 NSX
 BRV
 BRV
 DDV
 BRV
 } NDX
 NDX
 BRV
 BRV
 NDX
 BRV

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	SUNDRIES	1	\$ 80.00	\$ -80.00	NNX
2	TAILGATE SEALANT	1	\$ 100.00	\$ 30.00 100.00	NECV
3	TAILGATE OUTER GARNISH CLIPS	1	\$ 50.00	\$ 50.00	NNX
4	TAILGATE INNER TRIM BOARD CLIPS	1	\$ 50.00	\$ 30.00 50.00	NECV
5	TAILGATE LAMP SEAL	2	\$ 60.00	\$ 60.00 120.00	NECV
6	TAILGATE LAMP CLIPS	2	\$ 50.00	\$ 100.00	NNX
7	TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	\$ 40.00 100.00	NECV
8	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 20.00 60.00	NECV
9	TAILGATE WINDSCREEN PRIMER & CLEANER	1	\$ 80.00	\$ -80.00	NNX
10	REAR BUMPER CLIPS	1	\$ 50.00	\$ 30.00 50.00	NECV
11	REAR BUMPER LOWER CLIPS	1	\$ 50.00	\$ 30.00 50.00	NECV
12	REAR BUMPER ARCH GARNISH CLIPS	1	\$ 50.00	\$ 20.00 50.00	NECV
13	REAR END PANEL SEALANT	1	\$ 100.00	\$ 40.00 100.00	NECV
14	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 20.00 50.00	NECV
15	SPARE TYRE PANEL SEALANT	1	\$ 100.00	\$ -100.00	NNX
16	TAILLAMP SEAL	1 2	\$ 60.00	\$ 30.00 120.00	NECV
17	TAILLAMP CLIPS RH	1 2	\$ 50.00	\$ 30.00 100.00	NECV
18	REAR FENDER SEALANT	1	\$ 100.00	\$ -100.00	NNX
19	FENDER INNER TRIM BOARD CLIPS RH	1 2	\$ 50.00	\$ 30.00 100.00	NECV
20	REAR REVERSE CAMERA	1	\$ 480.00	\$ -480.00	NNX
21	REAR BUMPER REVERSE SENSOR	2	\$ 250.00	\$ 200.00 500.00	SCV
SPECIAL NETT TOTAL :				\$ 610.00 2,540.00	

Nos.	LABOUR	S\$	
1	R&R TAILGATE COMPONENT	\$ 80.00 150.00	
2	R&R TAILGATE WINDSCREEN	\$ 120.00 250.00	
3	R&R REAR BUMPER REVERSE SENSOR	\$ 60.00 100.00	
4	R&R REAR REVERSE CAMERA	\$ 100.00	NNX
5	CHECK WIRING	\$ 100.00	NNX
6	UPHOLSTERY	\$ 300.00	NNX
7	PANEL BEATING	\$ 1000.00 1,600.00	
8	RUST PROOFING	\$ 200.00	NNX
9	SPRAY PAINTING	\$ 800.00 1,600.00	
LABOUR TOTAL :		\$ 2060.00 4,400.00	

Survey 18/11/2021
Resurvey 19/11/2021
Lumpsum repair
Repair days 7

PARTS TOTAL : \$ 14,356.65

SPECIAL NETT TOTAL : \$ 2,540.00

LABOUR TOTAL : \$ 4,400.00

GRAND TOTAL : \$ 21,296.65

PARTS 8923.86
SN 610.00
LABOUR 2060.00
11,593.86
2318.77
9,275.09

LS 9250/r

Torin M

4/12/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: