

**QUOTATION**

Customer :

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBF7963U  
MAKE/MODEL : SYM / FIGHTER 150

*Not Approved*  
*all*  
*9/17/21*  
*2 days*  
*who plus A check up*

NO. : 39500

DATE : 16/11/2021  
CLAIM NO. : 11819  
POLICY NO. :  
FROM : RAYMOND

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER FRONT P/N: 40325 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	155.00 X
2	COVER SIDE LH ASSY (WHITE) P/N: 65409 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$82.00	82.00 X
3	COVER TOP P/N: 66165 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	94.00 X
4	COWLING FRONT (WHITE) P/N: 65538 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$168.00	168.00 X
5	FORK FRONT LH ASSY P/N: 69913 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$350.00	350.00 X
6	GASKET EXHAUST PIPE P/N: 38960 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00 X
7	HEADLAMP ASSY LH P/N: 36552 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$287.00	287.00 X
8	HEADLAMP ASSY RH P/N: 36551 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$287.00	287.00 X
9	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$63.00	504.00 X

\*39500 \*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

*bizSAFE<sub>3</sub>*



<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
LEVER BRAKE LH P/N: 38066 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	<i>alceser</i> 25.00 X
LEVER BRAKE RH P/N: 40634 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	<i>alceser</i> 27.00 X
12 METER VISOR ASSY BU-661S - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00	<i>117</i> 84.00 X
13 MIRROR ASSY LH P/N: 53140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	<i>117</i> 68.00 X
14 MIRROR RH P/N: 37494 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	<i>117</i> 70.00 X
15 MUDGUARD REAR P/N: 53361 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	<i>B20</i> 32.00
16 PIPE EXHAUST ASSY P/N: 37965 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$645.00	<i>117</i> 645.00 X
17 PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE <i>X</i>	1.00	\$27.00	<i>Set</i> 27.00 <sup>15</sup> / <sub>s/n</sub>
18 PROTECTOR CLUTCH COVER P/N: 38053 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00	<i>117</i> 59.00 X
19 PROTECTOR MUFFLER P/N: 38032 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	<i>alceser</i> 43.00 X
20 R SIDE COVER ASSY WH-010C/BK-001U P/N: 65408 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$73.00	<i>117</i> 73.00 X
21 SPOILER UNDER P/N: 65539 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$147.00	<i>alceser</i> 147.00 X
22 SPRAY PAINT ON REAR BOX - (REPORTED BY MECHANIC)	Spray <i>X</i>	1.00	\$250.00	<i>117</i> 250.00 X
23 STICKER (SINGAPORE POST) BOX REAR P/N: 39656 - (REPORTED BY MECHANIC)	REPLACE <i>X</i>	1.00	\$70.00	<i>117</i> 70.00 X
24 TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	<i>X</i>	1.00	\$55.00	<i>117</i> 55.00

*10%*

SUB TOTAL  
GST @ 7 %

*2-32*

\$3,611.00  
\$252.77

\*39500 \*

*bizSAFE<sub>3</sub>*



<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
<b>GRAND TOTAL (SGD)</b>				<b>\$3,863.77</b>

deposit required before ordering of parts.

validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge & Accepted By



**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Date of Submission: 08/11/2021 10:15 (GMT+8)  
 Date of Accident: 08/11/2021 10:15 (GMT+8)  
 Exact Location of Accident: Sims Way, Singapore  
 Additional Location Information:  
 Country/Area of Loss: Singapore

Vehicle Registration Number: PH7463U

Is company? Yes  
 Name of Registered Owner: Singapore Post Limited  
 Company Registration No: 192427  
 Road Address: 110, North Bridge Road, Singapore  
 Mobile Phone No: (Phone) +65 9221 7415  
 Alternative Phone No: (Fax) +65 434 1200

Manufacturer: Sun  
 Model: PROTEK 150 A  
 Version:  
 Check purpose for which vehicle was being used at time of accident:  
 Are you claiming under your own insurance policy for damage to your vehicle?  
 Vehicle Category: Motorcycle  
 Transmission: Auto  
 CC: 150

Name of Insurance Company: Sun Life of Canada General Insurance Limited  
 Type of Coverage: Third Party  
 Policy No: Yes  
 Policy Number: V0107834-AME  
 Cover Note Number:

\*39500 \*

Name of Driver: ANANTHARAJAL APPALADHAN  
 Valid Period: 6240X143K

Accident Report SJ0421300704

